

ASSIGNMENT

From: Date

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

758H

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SLL 6427H

Yr Regn:

3/3/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota hiace

cc

2982

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

184469

T/Radio:

Insured / Std / NI / NA

Eng/No

C/No

JTFST22P800029808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

22/12/20

D.O.I.

29/12/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Ref

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 80 Ambulance.
No market value for Ambulance

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation.

) S + RS. SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE 29/12/2020

MS First Capital Insurance Limited

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLL6427H

01)	1 PC	FRONT BUMPER	D/S ✓	\$	496.40
02)	10 PC	FRONT BUMPER CLIPS	rec ✓	\$	42.00
03)	1 PC	FRONT RH SIDE RETAINER	cna ✓	\$	193.10
04)	1 PC	FRONT RH FOG LAMP	garnish twi ✓	\$	68.10
05)	1 PC	FRONT RH HEADLAMP	scr ✓	\$	948.70
06)	1 PC	FRONT RH STEP PANEL	garnish twi ✓	\$	152.70
07)	1 PC	FRONT RH DOOR (REPAIR)	2 X	\$	-

	\$	1,901.00
LESS 25%	\$	(475.25)

	\$	1,425.75	
08) SPRAY PAINTING	\$	680.00	500
09) LABOUR CHARGE	\$	480.00	400
10) WIRING CHECK	\$	50.00	20
11) TUFFCOAT	\$	1180.00	X
12) ART WORK o/s door	\$	11280.00	150
	\$	2,995.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	758H
Vehicle Details	
Vehicle No.:	SLL6427H
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE HIGH ROOF COMMUTER TURBO AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2654471
Chassis No.:	JTFST22P800029808
Maximum Power Output:	-
Open Market Value:	\$49,425.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00
Message	

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 29 Dec 2020

OK