

NTUC-CIPD

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.12.2020

Time: 09:56:46

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440830
REGN NO : SHA1966G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 26.12.2020 08:15
ACCIDENT DATE : 24.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40 20.00 367.52
0002	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25 20.00 361.00
0003	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00 2.00- 50.00
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00 20.00 17.60
SUB-TOTAL :				796.12

Handwritten notes: 432.65, 746.12, SN 50, 796.12

JOB NATURE

QTY	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING	400.00	320
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
SUB-TOTAL :			780.00

Handwritten notes: 550

TOTAL : 1,576.12

Handwritten: \$1346.12, 2 days

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

- LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten: Worthy, Taufik 97495249, WP, 26/12/20 2:45pm, 2 days, Resurvey after repair, Taufik E. Lhamban.com