

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

28 Dec 20

INSURANCE

Budget Direct

DEL

HYUNDAI I40

VEHICLE NO

SFD 3193 R

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>Dep't 1</i>	1	\$2,285.90	\$2,285.90
BONNET RUBBER (LH) <i>Svc</i>	1	\$35.70	\$35.70
BONNET RUBBER (RH) <i>Svc</i>	1	\$35.70	\$35.70
BONNET HINGE (LH/RH) <i>dy</i>	2	\$128.70	\$253.40
BONNET LOCK <i>dy</i>	1	\$142.40	\$142.40
BONNET ABSORBER (LH ONLY) <i>Svc</i>	1	\$81.80	\$81.80
BONNET INSULATOR <i>ny</i>	1	\$202.50	\$202.50
BONNET INSULATOR CLIP 10 PCS <i>ny</i>	1	\$38.80	\$38.80
BONNET SEAL <i>ny</i>	1	\$31.90	\$31.90
BONNET INSULATOR CLIPS <i>ny</i>	1	\$15.00	\$15.00
BONNET CABLE <i>Svc</i>	1	\$89.80	\$89.80
RADIATOR GRILLE EMBLEM <i>broken/damaged</i>	1	\$129.50	\$129.50
RADIATOR GRILLE <i>broken</i>	1	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>broken</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>turn</i>	1	\$379.20	\$379.20
FRONT BUMPER REINFORCEMENT <i>Dep't</i>	1	\$588.40	\$588.40
FRONT BUMPER GRILLE (LH/RH) <i>o/s broken w/s ny</i>	2	(\$149.20)	\$298.40
FRONT BUMPER LIP <i>Svc</i>	1	\$152.00	\$152.00
FRONT BUMPER BRACKET TOP (LH/RH) <i>ny</i>	2	\$44.80	\$89.60
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) <i>MS1</i>	MS1	\$80.00	\$80.00
FRONT BUMPER BRACKET (LH/RH) <i>broken</i>	2	\$49.20	\$98.40
FRONT BUMPER SIDE BRACKET (LH/RH) <i>ny</i>	2	\$28.60	\$57.20
FRONT BUMPER PROTECTOR (LH/RH) <i>ny</i>	2	\$25.40	\$50.80
FRONT BUMPER RETAINER MOUNTING <i>ny</i>	1	\$76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (LH/RH) <i>ny</i>	2	\$126.20	\$252.40
WIPER CONTAINER ASSY <i>broken</i>	1	\$281.60	\$281.60
HEADLAMP SUPPORT PANEL ASSY <i>broken/st</i>	1	\$907.40	\$907.40
HEADLAMP (LH/RH) <i>mounting broken 1138 00 X 2</i>	2	\$2,776.00	\$5,552.00
HEADLAMP SUPPORT TOP COVER <i>st / wack / int</i>	1	\$222.60	\$222.60
HEADLAMP HALOGEN BULB (LH/RH) <i>ny</i>	2	\$28.80	\$57.60
RADIATOR <i>2 st</i>	1	\$1,637.20	\$1,637.20
RADIATOR GUARD (LH/RH) <i>Svc</i>	2	\$76.50	\$153.00
RADIATOR BRACKET (LH/RH) <i>ny</i>	2	\$13.00	\$26.00
COOLANT <i>ny</i>	1	\$ 45.00	\$ 45.00
RADIATOR FAN BLADE, COWLING, MOTOR ASSY <i>broken</i>	1	\$1,194.20	\$1,194.20
RADIATOR EXPANSION TANK <i>ny</i>	1	\$163.80	\$163.80
HORN UNIT (LH/RH) <i>o/s broken w/s ny</i>	2	\$73.80	\$147.60
HORN WIRE <i>ny</i>	1	\$156.60	\$156.60
FRONT FENDER (LH/RH) <i>o/s Dep't w/s reg</i>	2	\$663.00	\$1,326.00
FRONT FENDER APRON PANEL (LH/RH) <i>o/s Dep't w/s reg</i>	2	\$637.00	\$1,274.00
FRONT FENDER SHIELD (LH/RH) <i>ny turn / damaged</i>	2	\$174.90	\$349.80
FRONT FENDER MUDFLAP (LH/RH) <i>ny</i>	2	\$16.20	\$32.40
FRONT FENDER SIGNAL LAMP (LH/RH) <i>ny</i>	2	\$47.40	\$94.80

1110-10

708.50

792.95

FRONT FENDER RETAINER MS				
FRONT FENDER GUARD MS	1	\$24.60	\$24.60	X
AIRCON CONDENSER 2 1/4	1	\$120.00	\$120.00	X
FRONT WINDSCREEN SIDE GARNISH broken	1	\$947.80	\$947.80	2
FRONT WINDSCREEN GLASS black	1	\$298.00	\$298.00	✓
FRONT WINDSCREEN MOULDING New	1	\$1,017.80	\$1,017.80	✓
FRONT WINDSCREEN PILLAR OUTER (LH/RH) 0/3 1/4	1	\$133.70	\$133.70	✓
INTER COOLER 2 1/4	2	\$1,748.50	\$3,497.00	1535.40
	1	\$1,032.50	\$1,032.50	2
SUB TOTAL			\$28,821.80	18547.05
LESS 20%			\$5,724.36	14837.64
DISCOUNTED TOTAL			\$22,897.44	
FRONT NUMBER PLATE broken	SN 1	\$25.00	\$25.00	45/-
FRONT NO. PLATE TRIM COVER broken	SN 1	\$30.00	\$30.00	✓
FRONT WINDSCREEN SEALANT New	SN 1	\$46.00	\$46.00	✓
FRONT ERP STICKER New	SN 1	\$28.00	\$28.00	117.00
SUB TOTAL			\$127.00	
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	1200/-
Spray Painting Charge	1	\$1,400.00	\$1,400.00	1000/-
Wiring Charge	1	\$120.00	\$120.00	30/-
Tuff Kote	1	\$140.00	\$140.00	40/-
Towing Charge	1	\$80.00	\$80.00	40/-
Remove/Refix Radiator	1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box	1	\$120.00	\$120.00	40/-
Remove/Refix Front Windscreen Glass	1	\$120.00	\$120.00	80/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$4,350.00	2630.00
ESTIMATE TOTAL			\$ 27,374.44	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				

30/12/2020 c 0950hrs

Mr. Arundhan

2/Jan 12 days.

Mr.

LKK Auto

Check Part prices.
Provide BV before
Indication.

17584.64

Supp 6459.00

24043.64

1/5 16,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 4-Jan-21

MODEL: HYUNDAI I40

INSURANCE: Budget Direct.

VEHICLE NO.: SHD 3193 R (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
AIRCON SUCTION & LIQUID HOSE <i>1st</i>	1	\$624.00	\$624.00
AIRCON DISCHARGE HOSE <i>1st</i>	1	\$194.40	\$194.40
AIRCON COMPRESSOR <i>distorted 50% dep</i>	1	\$2,578.00	\$2,578.00
FAN BELT <i>turn</i>	1	\$182.70	\$182.70
FRONT SAFETY BELT ASSY (LH/RH) <i>distorted</i>	2	\$477.20	\$954.40
WIPER TOP GARNISH <i>broken</i>	1	\$476.60	\$476.60
FRONT CHASSIS MEMBER (RH) <i>1st</i>	1	\$1,060.70	\$1,060.70
AIR BAG CONTROL UNIT <i>distorted</i>	1	\$1,894.00	\$1,894.00
STEERING AIR BAG <i>distorted</i>	1	\$1,150.60	\$1,150.60
SUB TOTAL			\$9,115.40
LESS 20%			\$1,823.08
DISCOUNTED TOTAL			\$7,292.32

✓ 549.10
✓
✓ 1289.00
✓ SN
✓
✓
✓
✓
✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

1 nja

2KK Auto

04/01/2021

[Signature]

list SN
6462.50 1289.00
5170.00

6459.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date of Submission	28/12/2020 14:17 (SGT)
Date of Accident	23/12/2020 19:45 (SGT)
Exact Location of Accident	Kampong Kapur Rd, Singapore
Additional Location Information	KAMPONG KAPUR ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3193R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXXXX1R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	(Phone) +65-65508768
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	I40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi

INSURANCE COMPANY

Name of Insurance Company	India International
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	MCOM0015
Cover Note Number	-

DRIVER

Name of Driver	LAU KHENG HOCK
NRIC No	SXXXX047E
Date Of Birth	10/05/1968
Occupation	Outdoor

Case
Reference
Number
Phone Number
Address
Address
Address complement
Postcode

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

29/10/1990
30 YEARS AND 2 MONTHS
Male
(Phone) +65-96249559

FLEETSAFETY@CDGETAXI.COM.SG
BLK 227A COMPASSVALE LINK(ASPELLA)
#11-314
541277
No
Other
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
Yes
Yes
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Kampong Ubi Neighbourhood Police Post
(Phone) +65-18007479999
(Fax) +65-67453410
Blk 9 Eunos Crescent #01-2687 Singapore 400009
No

CIRCUMSTANCES OF ACCIDENT

REFER POLICE REPORT NO: T/20201224/2032
* TYPE OF ACCIDENT - HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver

SJQ5782K
-
-
-
-
Private car
-

INJURED 1

Name of injured person

Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

LAU KHENG HOCK

CHEST, BACK AND HAND
SHD3193R

Yes

Yes

sion.



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

started due to late reporting



T/20201224/2032

1 of 3

Report No. T/20201224/2032

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
24/12/2020 11:26

Vide Report No.:
A/20201223/0118

Station Diary No.:

Informant's Particulars

Name of Informant:
LAU KHENG HOCK

Address:
277A COMPASSVALE LINK #11-314 ASPELLA SINGAPORE
541277

ID Type / ID No.:
NRIC NO / S6822047E

Contact No.:
Home/Office: Mobile: 96249559

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male
Age: 52
Date of Birth: 10/05/1968

Type of Informant:
Driver

Race:
Chinese

Language:

Institution / School Name:

Occupation:
Taxi driver

Driving Licence Information:
Class: 2B,3

Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/12/2020 19:45	Type of Location:
Location: KAMPONG KAPOR ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume: Heavy		
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD3193R	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue		0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

**SINGAPORE
POLICE FORCE**



T/20201224/2032

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20201224/2032

CONTINUATION OF REPORT

Driver				
Name	LAU KHENG HOCK		ID No.	S6822047E
Related Vehicle	SHD3193R (Car)		Contact No.	96249559
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	23/12/2020		Date Discharge	24/12/2020
No. of Days granted Medical Leave	03	Degree of Injury	NIL	

Brief Details.

On the stated date, time and place,

I was driving along Kampong Kapur Rd slowly to pick up a passenger. The traffic was very heavy. Suddenly, at a small junction, a private car came very fast from my right. He was coming from Veerasamy Rd. He should have stopped and given way for me to drive past, but he did not do so. I did not have time to react. The private car hit onto my front right side. My airbag inflated. I was injured. Soon, the traffic police and SCDF arrived. The paramedics checked me and asked me to be conveyed to the hospital for further check-up. Case is under IO Muhaimin, Ext: 6547 6090. That's all.

SINGAPORE
POLICE FORCE



T/20201224/2032

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20201224/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
SC NAFEEES ABDUL KADER

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt NUR ADELINA BINTE MOHAMMAD
FUAT
Contact No.: 65476066

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
24/12/2020 11:26

Classification Of Case:



SINGAPORE
POLICE FORCE

Signature:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 26.12.2020
@ 12:15 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A - SHD 3183R
B - SJO 5782K



Along Kapong Kapor Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20201224/2032

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Date & Time: 28.12.2020
@ 12:15 hrs

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: