


ASS. REC. BY: Stere REF: AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Val. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

MR-52K

ale/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

ale/Time, File Return to?

ap. Formes :

mp Sum / L.E.J. /

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Veh No: SLZ 1928 M Yr Regn: 26/4/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1193
 Make: Mitsubishi Attrage c.c. 1291
 Colour: White A/C: Insured / Std / NI / N
 Sp. Reading: 43946 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: MMBSTA JH021855
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R15
 R: _____
SSA DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or \$ _____
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 28/12/21 p.o.i. 29/12/20
 Survey held at Cycle & Carnap
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name /Lee Heok Yong Reg No/Reg Date SLZ1928M / 26/04/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH001855 Engine No 3A92UGS5536 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|---|--------|-------------------|-----|---------------|------------|-------|---------|
| KAX00008 | Credit | 29/12/2020/ 12:49 | QUD | 247 / DonBong | 61278 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH REAR DOOR, REPAIR REAR BUMPER, REAR BODY KITS, REPAIR RH REAR FENDER, REPAIR RH SIDE SKIRTING, REPAIR RH FRONT DOOR, | | | | 2 x 450 | | | 1800.00 |
| E PNT88000 TRANSFER RH REAR DOOR TRIM, DOOR GLASS, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL | | | | | | | 120.00 |
| E PNT98000 PAINT WORK SPRAY RH REAR DOOR, REAR BUMPER, REAR BODY KITS, RH REAR FENDER, RH SIDE SKIRTING, RH FRONT DOOR AND AFFECTED PORTION | | | | 350 x 6 | | | 2450.00 |
| M SUNDRY APPLY BODY SEALANT | | | | | | | 80.00 |
| A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | | | | | | | 30.00 |
| M SUNDRY PERFORM RUST PREVENTION | | | | | | | 80.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | | | 120.00 |
| A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment | | | | | | | 30.00 |
| M SUNDRY LABOUR RENEW RH REAR SPORT RIM INCLUDNG BALANCING | | | | | | | 50.00 |
| M SUNDRY SUNDRIES | | | | | | | |
| M PANEL ASSY,RR DOOR,RH | | | | 1.00 | 799.00 | 23.00 | 615.23 |
| M TAPE,RR DOOR SASH,RH | | | | 1.00 | 29.00 | 23.00 | 22.33 |
| M BRACKET,RR BUMPER,LH | | | | 1.00 | 28.00 | 23.00 | 21.56 |
| M BRACKET,RR BUMPER,RH | | | | 1.00 | 28.00 | 23.00 | 21.56 |
| M CLIP,RR BUMPER | | | | 10.00 | 4.00 | 23.00 | 30.80 |
| M WHEEL,DISC | | | | 1.00 | 687.00 | 23.00 | 528.99 |

Estimate

DO

PEC

X

9

CUT

STEVE CLKK

WHL

PL

SURVEYOR NAME: SURVEYOR SIGNATURE:

Estimate

Confirm & accepted by

DATE: 29/12/20, 1:30 pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party authorized signatory and company stamp

REMARKS: 5 days PIP

7% GST on

Nett
6120.476,120.47
428.43

Total Payable

6,548.90

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|--|
| Date of Submission | 29/12/2020 13:17 (SGT) |
| Date of Accident | 28/12/2020 18:05 (SGT) |
| Exact Location of Accident | 587 Bukit Timah Rd, Singapore 269707 |
| Additional Location Information | BUKIT TIMAH ROAD TOWARDS CAVENAGH ROAD |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ1928M

INSURED/POLICYHOLDER

| | |
|--------------------------|--------------------------|
| Is company? | No |
| Name Of Registered Owner | LEE HEOK YONG |
| NRIC No | SXXXX756I |
| Email Address | LEE.YH.FRANCIS@GMAIL.COM |
| Mobile Phone No | (Phone) +65-91466448 |
| Alternative Phone No | +65-91466448 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Mitsubishi |
| Model | Attrage |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | - |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |

INSURANCE COMPANY

| | |
|---------------------------|---------------|
| Name of Insurance Company | AIG |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | 1800038327 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|--------------|
| Name of Driver | KONG MING-LI |
| NRIC No | SXXXX301D |
| Date Of Birth | 14/03/1970 |
| Occupation | Indoor |

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

25/07/2002
 18 YEARS AND 5 MONTHS
 Female
 (Phone) +65-90170016
 -
 LEE.YH.FRANCIS@GMAIL.COM
 BLK 123 BISHAN STREET 12 #07-15
 -
 570123
 No
 Relative
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Side Swipe
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 1
 No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Police Station Name
 Police Station Phone No
 Alt. Police Station Phone No
 Police Station Address
 Was notice of intended Prosecution given?
 If yes, against whom?

Yes
 Tanglin Division Headquarters
 (Phone) +65-18003910000
 (Fax) +65-63964900
 21 Kampong Java Road Singapore 228892
 No
 -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes
 No
 No

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 Contact Number

SKX497T
 Mazda
 -
 -
 -
 Private car
 BEN WEI LUN
 (Phone) +65-92717313

Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
AIG
-
-
-


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 29/12/2020 1020 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Bucket Timah Rd → KK Hospital



Cavenagh Rd

Island

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The road our Car (SLZ 1928N; driven by Ms. Kong Ming Li - S7609301D) was on had three (3) lanes.

We were on middle lane when a Certis Auxillary car (SKX 497T) driven by Mr. Beh Wei Lun, of License number S 8985606Z, Collided into our Car from the right Side of driver to back passenger door till back fender.


Certis Car (SKX 497T) had their left fender damaged. No injuries were Sustained by the driver and his passenger Mr. Lui Tian Wee, (Edmond; S9527103I) as Communicated by them.

The weather was fine, and the roads were dry with good visibility.

Pls refer attached picture.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 29/12/2020
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



E/20201228/7039

1 of 2

POLICE REPORT (NP299)

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No:1800-3910000

Report No. E/20201228/7039

| | | |
|---|---|---------------------|
| Date/Time Report Made 28/12/2020 21:57 | Vide Report No. | Station Diary No. |
| Name Of Informant LEE HEOK YONG | Address 122 BISHAN STREET 12 #05-37 SINGAPORE 570122 | |
| ID Type / ID No. NRIC NO / S7701 756I | Contact No. Home/Office: | Mobile: 91466448 |
| Nationality SINGAPORE CITIZEN | Email Address lee.yh.francis@gmail.com | |
| Occupation Operations | Sex Male | Age 60 |
| Institution/School Name | Date of Birth 20/04/1960 | Race Chinese |
| Date/Time Of Incident 28/12/2020 18:05 | Location Of Incident BUKIT TIMAH ROAD | |

Brief details.

The road our car (SLZ1928M; driven by Kong Ming Li – S7009301D) was on had three lanes. We were on the middle lane when a Certis Cisco Auxiliary police car (SKX497T) driven by Beh Wei Lun, of license number S8985606Z, collided into our car from the right rear end. The weather was fine, and the roads were dry with good visibility. Damage was sustained on the right side of our car (see attached picture), and on the other car on their front left fender (see picture). No injuries were sustained by the driver and one passenger (Lui Tian Wen, Edmund; S9527103J) of the other car as communicated by them.

Subjects Involved

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:
The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
28/12/2020 21:57

Classification Of Case:



SINGAPORE POLICE FORCE



E/20201228/7039

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20201228/7039

| Victim | | | |
|-------------|---------------------------|------------------------|--|
| Person Name | LEE HEOK YONG | | |
| ID Type | NRIC NO | ID No | 91466 7561 |
| Gender | Male | Age | 60 |
| Race | Chinese | Language | English |
| Occupation | Operations | Address | 122 BISHAN STREET 12 #05-37 SINGAPORE 570122 |
| Mobile No | 91466448 | Is Informant A Victim? | Yes |
| | | | |
| Person Name | Kong Ming Li | ID No | 91466 301D |
| ID Type | NRIC NO | Age | 50 |
| Gender | Female | Language | English |
| Race | Chinese | Address | 123 Bishan st 12 #07-15 SINGAPORE 570123 |
| Occupation | Business owner | | |
| Mobile No | 90170016 | | |
| | | | |
| Person Name | LEE HEOK YONG (Informant) | | |

1

| | |
|--|--|
| Signature Of Officer Recording The Report: Not applicable | Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required. |
| Signature Of Interpreter: Not applicable | Date/Time: 28/12/2020 21:57 |
| Officer In-Charge Of Case: | Classification Of Case: |
| Authentication Stamp | |

CERTIFICATE OF INSURANCE

VEHICLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEE HEOK YONG
 Period of Insurance : 26 Apr 2020 To 25 Apr 2021
 Engine No. : 3A92UGS5536
 Chassis No. : MMBSTA13AJH001855

Vehicle No. : SLZ1928M
 Policy No. : 1800038327-01
 Endorsement No. :
 Issued Date : 06 Apr 2020

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
 Engine Capacity/Tonnage : 1,193.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE HEOK YONG - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620207

C&CMICP2 - KERENY

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPYJJ

1003176574/AC