

Yee Auto Pte Ltd

160 Sin Ming Dr #02-17 / #07-12 Sin Ming Autocity Singapore 575722
 TEL: 6457 5768 FAX: 6252 8459 Email: yeeautopteLtd@gmail.com
 GST:201719251W RCB No:201719251W

M/S : AXA Insurance Pte Ltd
 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811.

Not Authorized
1/1 Pay @
Money After Pain
4 days

Estimate No: **ES2000121**
 Date: 31 Dec 2020
 Policy No:
 Veh Reg No: **SMG8091T**
 Make/Model: **TOYOTA WISH 1.8X A**
 Chassis No: **ZGE200011057**
 Engine No: **2ZR0432989**
 Reg. Date: 14/08/2009

ATTN: Motor Claim Department
 Your Ref No: -
 Claim Type: Third Party
 Accident Date: 22/12/2020
 TP Veh Reg No: SJQ8512D

Estimate Repair Cost to Vehicle No :SMG8091T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 PARKING SENSOR	300.00	1 SET	<i>See</i> 300.00 X	300.00
Spare Parts				
2 FRONT BUMPER	955.80	1 PC	<i>R</i> 955.80 ✓	
3 FRONT BUMPER CLIPS	40.00	1 SET	<i>see</i> 40.00 ✓	
4 FRONT BUMPER FOG LAMP - RH	328.10	1 PC	<i>see</i> 328.10 X	
5 FRONT BUMPER FOG LAMP COVER - RH	125.00	1 PC	<i>see</i> 125.00 X	
6 FRONT BUMPER REINFORCEMENT	365.50	1 PC	<i>R</i> 365.50 X	
7 FRONT BUMPER SIDE RETAINER - LH	36.30	1 PC	<i>see</i> 36.30 X	
8 FRONT BUMPER SIDE RETAINER - RH	36.30	1 PC	<i>ditto</i> 36.30 ✓	
9 FRONT BUMPER SPONGE	195.90	1 PC	<i>see</i> 195.90 X	
10 FRONT FENDER - RH	544.00	1 PC	<i>R</i> 544.00 X	
11 FRONT FENDER SPLASH SHIELD - RH	245.30	1 PC	<i>see</i> 245.30 X	
12 FRONT FENDER SPLASH SHIELD CLIP	40.00	1 SET	<i>see</i> 40.00 X	
13 FRONT GRILLE	285.50	1 PC	<i>see</i> 285.50 X	
14 FRONT HEADLAMP - RH	825.10	1 PC	<i>see</i> 825.10 ✓	
			4,022.80	4,022.80
Labour				
15 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	<i>3600</i>
16 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	<i>4000</i>
17 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	<i>200</i>
			1,660.00	1,660.00

250

Total S\$ 5,982.80

Add GST @ 7% 418.80

Total Amount Payable S\$ 6,401.60

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED AND ONE AND CENTS SIXTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/12/2020 17:26 (SGT)
Date of Accident 22/12/2020 08:00 (SGT)
Exact Location of Accident Ang Mo Kio Ave 10, Singapore
Additional Location Information BLK 531 / 532 AVE 10 ANG MO KIO OPEN CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG8091T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner KHANG LAI SOON
NRIC No SXXXX852J
Email Address SOONLY71@HOTMAIL.COM
Mobile Phone No (Phone) +65-91875200
Alternative Phone No (Office) +65-91875200

VEHICLE PARTICULARS

Manufacturer Toyota
Model Wish
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company FWD
Type of Coverage Comprehensive
Fleet Policy No
Policy Number PNPV2020-00002010
Cover Note Number 25/04/2020 TO 24/04/2021

DRIVER

Name of Driver KHANG LAI SOON
NRIC No SXXXX852J
Date Of Birth 19/12/1971
Occupation Outdoor

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

12/03/1994
 26 YEARS AND 9 MONTHS
 Male
 (Phone) +65-91875200
 (Office) +65-91875200
 SOONLY71@HOTMAIL.COM
 BLK 590B ANG MO KIO STREET 51 #29-27

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Major/Minor Rd
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 2
 No

PASSENGER 1

Name
 Gender

NG WEI MIN ADEELA
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?


Yes
 No
 No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 Contact Number

SJQ8512D
 -
 -
 -
 -
 Private car
 -
 -

Date of accident: 22/12/2020 Time: 8:00am Location: Blk 531 X 532 Ang Mo Kio Ave 10
 My Vehicle A: SMG8091T Vehicle B: SJQ8512D Vehicle C: Open Carpark
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/2020 at 8:00am. I was travelling my vehicle (A) SMG8091T along Blk 531 & 532 Ang Mo Kio Ave 10 Open Carpark. As I reversed into the carpark lot and half complete, suddenly, the vehicle (B) SJQ8512D from my right side reverse with high speed and hit onto my vehicle right portion.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only
 Yee Auto Pte Ltd
 yeeautoptehd@gmail.com
 * Kindly email my CIA report to me and my workshop Yee Auto Pte Ltd


Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
22/12/2020
AH LIM MOTOR COMPANY

GIARMC SketchPlanForm_V3