



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving

TPVD TBC (SMG8091T)

Date of Loss

22 December 2020

Time of Loss

0.00

Loss Description

SJQ8512D (INSD) C/W SMG8091T

Comment

Workshop Details

Total Rebate Amount

29469

Nett Loss Amount

\$17,531.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SMG8091T

Registration State

SINGAPORE

Mileage

187692

Purchase Date

dd/mm/yyyy



Registration Date *

14/08/2009



Age of Vehicle

11

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2009

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Make

POLICY INFORMAT... TPVD

ASSESSMENT INFO...

TOYOTA

CATEGORY Model

POLICY INFORMAT... TBC

ASSESSMENT INFO...

WISH 1.8X A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...



CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

ZGE200011057

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... 2ZR0432989

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1797

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 47000

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

31/12/2020 

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Condition of Vehicle at time of survey

General condition

Good 

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good 

Tyre Condition

Spare wheel

Front Tyre Size

Front left side

Front right side

Rear Tyre Size

Rear left side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

 Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BUMPER	Bent	0	648	No		25			486	Reviewing
<input type="checkbox"/>		0	1		SET FRONT BUMPER CLIPS	Necessary	0	40	No		25			30	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP - RH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP COVER - RH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER REINFORCEMENT	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - LH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - RH	Damaged	0	36.3	No		25			27.23	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER SPONGE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER - RH	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER SPLASH SHIELD - RH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET FRONT FENDER SPLASH SHIELD CLIP	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT GRILLE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT HEADLAMP - RH	Cut	0	825.1	No		25			618.83	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	0	360	0	0	Reviewing		
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	0	400	0	0	Reviewing		
<input type="checkbox"/>		0		TO CHECK WIRING FUNCTIONS	0	20	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[Add](#)[Approve](#)[Deny](#)[Submit All](#)

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	SET PARKING SENSOR	Deny		0	SERVICEABLE	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$1,942.06

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$1,162.06

Labour

\$0.00

\$780.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		1550		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$1,550.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$1,550.00

Submit for Review