

ASS. REC. BY: Sun Pin

REF:

CS/A1620014693/Qq d3.**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____


Policy No. 1700084952Claims No. 4419439939SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBS 8875R Yr Regn: 22/04/2009Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Scania K4x2 C.C. 9290Colour: Multicolour A/C: Insured / Std / NI / NASp. Reading: 896376 T/Radio: Insured / Std / NI / NAEng/No: -C/No: Y52K4X20001863747

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70 R22.5R: 275/70 R22.5BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 29/12/2020Survey held at SBS TransitDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Submit final fig \$490, 1 day.

Date/Time, File Pass to?

1) 20/01 Typist

Date/Time, File Return to?

2)

Report Format: MER-TP490Days Of Repair: 1

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	653M
Vehicle Details	
Vehicle No.:	SBS8875R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2020
Vehicle Make:	SCANIA
Vehicle Model:	KUB4X2 9.3L A/T ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2008
Engine No.:	6424637
Chassis No.:	YS2K4X20001863747
Maximum Power Output:	-
Open Market Value:	\$320,763.00
Original Registration Date:	22 Apr 2009
First Registration Date:	22 Apr 2009
Transfer Count:	0
Actual ARF Paid:	\$16,039.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 30 Dec 2020

OK

ΛΟΥΙΣ

Vehicle No: SBS 8875R

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	991485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1103	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1125	995326	Frt LH Door			
1126	995140	Frt LH Door Protector			
1127	995104	Frt LH Door Hinge			
1128	995142	Frt LH Door Wing Mirror			
1126	995103	Frt LH Door Glass			
1126	991595	Frt LH Door Glass Regulator			
1126	991596	Frt LH Door Glass Regulator Motor			
1126	991662	Frt LH Door Rubber			
1126	991636	Frt LH Door Outer Handle			
1127	991617	Frt LH Door Inner Trim Board			
1131	995327	Frt RH Door			
1131	991654	Frt RH Door Protector			
1131	991601	Frt RH Door Hinge			
1131	991685	Frt RH Door Wing Mirror			
1132	991584	Frt RH Door Glass			
1132	991595	Frt RH Door Glass Regulator			
1132	991596	Frt RH Door Glass Regulator Motor			
1132	991662	Frt RH Door Rubber			
1132	991636	Frt RH Door Outer Handle			
1133	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	991498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		Side panel			

No of Items:

3

Assessor: Sun Pin