

12/12/2020

REF: CS/CTI20014698/d3

Special Instruction:

ASS. REC. BY:

SURVBY

Merimen

ASSIGNMENT (Office)

From (Person): ADELINE CHNG

of CTI

Date/Time: 29/12/2020@3.01PM

Estimated Cost:

Bill to:

OD ☒ TP WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 4714A

Insured: SJR 4779Y

at Workshop m/s TICK HAI MOTOR

Tel: 6842 9089

of 1 KAKI BUKIT AVE 6 # 01-54

Policy No: DMPCSNW00172662000

Claim No: SNM20D205118/C02/CHNGPW

Sum Insured:

Excess:

D.O.A. 23/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time 3.36PM@29/12/20

Person Contacted: CONNIE

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 30/12/2020
	SLA 4714A-X	
	SJR 4779Y-X	