ASS. REC. BY: Sun Pin Cs/CT120014700/Qad ASSIGNMENT From: SKX 5287A Yr Regn: 17/12/2015 Veh No: Estimated Cost: Type: (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / OD TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: Make: c.c 1496 Mazda 3 at Workshop m/s Blue Insured / Std / NI / NA Colour A/C: T/Radio: Insured / Std / NI / NA Sb.Reading 47118. Insured: Eng/No: Policy No. DMPCSNW00156322000 JM6BM 42A860326426 C/No: Claims No. SNM20D205060C01 Gen. Cond: Good (Fair / Poor / Burnt Sum Insured: Steering: In order / Jammed / Leaked / Burnt or Excess: (Client's Record) Brake: In order Jammed / Leaked / Burnt or Make of Veh: Modi: Nil (S/Rim) STD A/Rim or R16 205/60 Tyre Size: (Policy Condition) 205/60 R16 Remark: The veh had commenced its OIS N/S BSÎ)DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Rear IDAC Accident Rport: Consistent?: Yes or No R/Bal. R/Bal. mm GIA / PR Seen: Consistent?: Yes or No L/Bal. Ľ/Bal. mm mm D.O.A. 21/12/2020 D.O.I. 30/12/2020 Res.: Yes or No Est. Repairs: davs 3 Val.: Yes or No ٥/۵ Survey held at Auto Inssure Lum Sum: Des. of Damages (: Frt) Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Action / Instruction Date / Time 31/12/20@10.59am revert to Jenny Lew via Merimen. MV: 50,000 37,232 NY: 12,768 : Preli. Report Days Of Repair: Date/Time, File Pass to? Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? Add Fee: : Site Insp S+RS. Photos :Interview (\$:Tech. Invs (\$ Others Reputer ormed: Weellend (\$ Lump 2000 / LE. E. CF TOTAL

KEF:

SA1A20CM0001 / Auto Insure Pte Ltd [739145] SATIZZOWIO 17 AUGI INSIGE FE EU [753145] ENTRY DATE & TIME: 22/12/2020 14:26 (SGT) SUBMITTED BY: ALYWIN YEO VERSION: 1 (22/12/2020 14:26 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/12/2020 14:26 (SGT) Date of Accident 21/12/2020 17:15 (SGT) **Exact Location of Accident** PIE, Singapore Additional Location Information PIE CHANGI TWDS UPP SERANGOON EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX5287A

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner QUEK CHEE YANG NRIC No SXXXX680E **Email Address** GODRICQUEK@GMAIL.COM Mobile Phone No (Phone) +65-98339084 Alternative Phone No (Home) +65-67494252

VEHICLE PARTICULARS

Manufacturer Mazda Model 3 Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to

vour vehicle? Yes

Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance Type of Coverage Comprehensive Fleet Policy No **Policy Number** DMPCSNW00156322000 Cover Note Number

DRIVER

Name of Driver **QUEK CHEE YANG** NRIC No SXXXX680E Date Of Birth 10/09/1990 Occupation Outdoor

Date Of Driving Pass 15/12/2015 Driving experience 5 YEARS Gender Male Mobile Number (Phone) +65-98339084 Alt. Phone Number (Home) +65-67494252 Email Address GODRICQUEK@GMAIL.COM Address BLK 322 UBI AVE 1 #05-601 Address complement Postcode 400322 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Collision - Head to Rear

Clear

Road Surface

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

No
Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Yes
Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

Yes

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

VEHICLE B RECKLESS DRIVING SWERVE INFRONT OF VEHICLE A SUDDENLY AND JAM BRAKE, VEHICLE A BRAKES IMMEDIATELY BUMP INTO VEHICLE B. NO ONE WAS INJURED.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

ostcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN		
pescribe circumstances of the	B A CODENT	A-SKX S287A B-SBF 7B
		1.100 WE VEHICLE A
VEHICLE IS WREULE	S PRIVING SWERVE	SCHOOL MARBINTELY
SUPPENCY AND	SKINE VIENCE A	ufulters
BOMP JATO VEHILL	LE B. NO DAIE WAS IN	d Je KETJ
DECLARATION		
I/We declare the foresting particulars.	are true in every respect.	
Fol cyholcer's Sanattre	Driver's Signature (If driver is not the policyholder)	Reporting centre Personnel's Signature Name
22/n/2020	Date & Time:	NRIC/FIN No .

Auto Insure Pte. Ltd 6 Marsiling Lane 739145

Insurer Reference: M1307 Repairer Reference: SKX5287A

Date calculated: 28/12/2020 10:39 AM



Full Report Registration: SKX5287A

Printed: 28/12/2020 10:39 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

Sam Goh M1307 Currency:

SGD

Estimated Repair Time:

Actual Repair Days:

Date of Incident: Hire Car Start: Hire Car End:

21/12/20

Vehicle Details

Vehicle

Manufacturer:

MAZDA

Model:

3 (BM/BN) BASE MODEL

Sub Model: Model Sheet Number:

36 68 01

Registration:

SKX5287A

VIN number: Odometer:

Model Specs

FROM 05/2016

FOG LAMPS

4-DOOR SALOON

TWO COAT METALLIC

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All

Underbody



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Audatex System Using Manufacturer Times

Page 1 of 4

PRINT DATE 28/12/2020

S0201F-K-X	KENEW FRONT BUMPER AND NECES	CARV			
	INCLUDES: R + R BUMPER AND NECES	SART			
S0204A-R-X)	ATTACHED PARTS RENEW RADIATOR GRILLE			5.0	21.00
T0301A-R-X)	R + R L/F HEADLAMP			3.0	12.60
10301A-K-X)	(BUMPER REMOVED)				
	DOES NOT INCLUDE: ADJUST HEADLAN	1P			
T0301A-R-X)	R + R R/F HEADLAMP			3.0	12.60
10301A-K-X)	(BUMPER REMOVED)				
	DOES NOT INCLUDE: ADJUST HEADLAM	1P			
S0612B-R-X)	The state of the s			9.0	37.80
0475	L/BONNET HINGE REPAIR		Ç	10.0*	42.00
0476	R/BONNET HINGE REPAIR		E	10.0*	42.00
0741	L/F WING REPAIR		×	15.0*	63.00
0742	R/F WING REPAIR		1.796	15.0*	63.00
0742	141 112110 112111111				
	Labour Cost		Hrs	WU	
	Panel / Mechanical Labour		7.70	77.0	323.40
	Total of Labour				323.40
Paint					
Paint Work	SYSTEM	AZT	Tiı	ne Basis	s 10 WU/h
				WU	Price SGD
Code	Description - TWO COAT METALLIC			***	Price 30D
	FRONT BUMPER NEW PART PAINT K1R			11.0	
	L/F WING REPAIR PAINTING <50%			11.0	
	R/F WING REPAIR PAINTING <50%			11.0	
Paint Materia	al Per Part				
Code	Description				Price SGD
	EDONT DUMPED NEW DART DAINT VID				52.64
0281	FRONT BUMPER NEW PART PAINT K1R L/F WING REPAIR PAINTING <50%				13.57
0741	R/F WING REPAIR PAINTING <50%				13.57
0742	KJF WING REPAIR FAINTING \30 /0				
	Labour Cost - Paint		Hrs	wu	Price SGD
	Factor	42.00 SGD/h	5		
	Time Paint	42.00 555/11		33.0	
	Preparation Main Work Metal		2.10	21.0	88.20
	Preparation Comp. Work Plastic		0.50	5.0	21.00
	Total	10 WU/h	5.90	59.0	247.80
	Material Cost - Paint				Price SGD
	New Part Painting - Plastic K1R				52.64
	Repair Painting				27.14
	Material-constant Metal				18.10
	Material-constant Plastic				9.00
	Total				106.88

Description

RENEW FRONT BUMPER

S0201F-R-X

WU Price SGD

7.0

29.40

pare Parts

			nrices as a	t 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
0281	FRONT BUMPER	B63B50031BBB	Original / CRU	400.00
1009	FRONT PANEL	BJS753110B	Original A CRA	265.00
0349	FRT BUMPER GRILLE	BHN150712B		55.00
0340	FRT BUMPER SUPPORT	BJS750070C		220.00
0283	L/BUMPER BRACKET	BHN1500U1E	3	15.00
0369	L/F BUMPER MOULDING		Original X	75.00
0561	L/F HEADLAMP		Original WAAX	
0433		BAAN510L0E	Original	385.00
	MANUFACTURER BADGE			0.00
0284	R/BUMPER BRACKET	BHN1500T1F	Original / ßk	15.00
0326	R/BUMPER COVER	B63B50101	Original /i/uડ	20.00
0370	R/F BUMPER MOULDING	B63B507J1A	Original /CRA	75.00
0562	R/F HEADLAMP	BJF4510K0A	Original /CRA	385.00
1355	UPPER FRONT PANEL	B45A53150A	Original / BT	110.00
1351	UPP INN FRONT PANEL	BHN1501C0B	Original 7	70.00
0323	UPP RAD GRILLE COVER	BANE50033A51	Original 7	165.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,255.00
u: Used parts	Total			2,255.00

Extras

Code	Description	Price SGD
1000	CAR PLATE / C RV.	25.00* 25.00

Repair day - 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

before puits photo.

OD - Rev.

Fex (45) = TBA

PIP

Sun Pin (Llik) 30/12/2020

nal Calculation

	SGD	SGD
Parts	2,255.00	
Total Parts	_,	2,255.00
Labour Time Base 10 WU/h		
Total 77.0 WU X 42.00 SGD/h	323.40	
Total of Labour	323.10	323.40
Total Of Extras		25.00
Paint Work Time Base 10 WU/h		
Labour Cost 59.0 WU X 42.00 SGD/h	247.80	
Material Cost	106.88	
Total Paint Including Material		354.68
Repair Cost Excludes GST		2,958.08
GST (+7.00%)	,	207.07
Repair Cost Included GST		3,165.15
Deductions (Excludes GST)		
Deduction For Excess	-500.00	
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		2,458.08
GST (+7.00%)		172.07
Grand Total Included GST		2,630.15

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	680E
Vehicle No.:	SKX5287A
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	P520335296
Chassis No.:	JM6BM42A8G0326926
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,812.00
Original Registration Date:	17 Dec 2015
First Registration Date:	17 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$12,812.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2025
PARF Rebate Amount:	\$8,968.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$28,264.00
Total Rebate Amount:	\$37,232.00

The information contained herein is correct as at 30 Dec 2020

ОК

,





prices and other information displayed on squarmart.com are gamered from sources and based on algorithms that are believed by squarmart.com to be reliable, but no assurance can be give that this information is accurate, complete or current. sqCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2020 sgCarMart, Singapore. All rights reserved.

Compare