

ASS. REC. BY:

REF:

AIG / 200

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 2524H Yr Regn: 10, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A909 c.c. 1496

Colour:

White A/C: Insured / Std / NI / NA

Sp. Reading:

88074 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NHP10 236885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Pn wide 195/55R15

Kapsen R: Pn wide

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

4 mm

L/Bal.

6 mm

L/Bal.

4 mm

D.O.A.

27/12/20

D.O.I.

29/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 28.12.2020
 Vehicle No: SLH2524H
 Model: TOYOTA AQUA HYBRID 1.5S
 Chassis: NHP102568851-2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SDA1318A
 Date of Accident: 27.12.2020

NOT Authorised
6/1/2021
Recovery After Paint

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bz</i> \$848.70 ✓
2	REAR BUMPER SIDE BRACKET LH	1		<i>nit</i> \$64.40 ✓
3	REAR BUMPER REINFORCEMENT	1		<i>n</i> \$590.60 x
4	REAR TAIL LAMP LH	1		<i>Sen</i> \$530.20 ✓
5	REAR FENDER AIR VENT LH	1		<i>in</i> \$55.80 x
6	REAR FENDER INNER LINER LH	1		<i>in</i> \$129.60 x
7	REAR END PANEL	1		REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

SUB TOTAL	\$2,219.30
LESS 25%	-\$554.83
PARTS TOTAL	\$1,664.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS <i>Acknowledged by Repairer</i>	1		<i>na</i> \$50.00 ✓
2	REAR BUMPER REVERSE SENSOR	1		<i>in</i> \$300.00 x
3	REAR FENDER INNER LINER CLIPS LH	1		<i>nn</i> \$35.00 x
S/N TOTAL				\$385.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$400.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL & ETC.

\$500.00 *300*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 *200*

LABOUR CHARGES TO REMOEV & REPLACE REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

\$100.00 *500*

LABOUR TOTAL \$1,080.00

TingAn TOTAL \$3,129.48

Head office

8 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
 Tel: (+65) 6484 9019 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
 Tel: (+65) 6461 1522 | Fax: (+65) 6461 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	455W
Vehicle Details	
Vehicle No.:	SLH2524H
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	AQUA HYBRID 1.5S AT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1NZ8023089
Chassis No.:	NHP102568851
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$20,727.00
Original Registration Date:	27 Oct 2016
First Registration Date:	27 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$30,005.00
Total Rebate Amount:	\$33,755.00

The information contained herein is correct as at 28 Dec 2020

OK