

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

① TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 0999993937 778E

Claims No. 6557903244SG


Sum Insured: _____ Excess: 1400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 837K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBE 7515K Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Peugeot Partner c.c. 1560

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 164342 T/Radio: Insured / Std / NI / NA

Eng/No: 7

C/No: VF 3F 9H F 8 F J 8 7 9 1 6 3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size: Windforce 195/65R15

R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/12/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/12/20 @ 10.15am revert to AIG via Merimen.

06/01/21 @ 9.07pm Kok Chong informed C/A via Merimen.

07/01/21 @ 10.18am Informed Candy C/A & ex: \$1400 by email.

Kenneth confirmed final fig \$3213.50, 4 days. (Red \$3794.80, 54%)
(No Lump Sum)

Date/Time, File Pass to?

☐: Prell. Report

1) 29/01 Typist

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

Report Format: MER-OD

Lump Sum / I.B.I: (\$ 3213.50



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

ATTN : ACCOUNTS DEPT

TEL : 6849 8118

FAX :

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 11/12/2020

ESTIMATE

NO : QUOT202012-000065(00)

DATE : 30/12/2020

POLICY NO : 999995580

VEH REG NO : GBE7515K

MAKE/MODEL : PEUGEOT PARTNER 1.6 HDI
ETG LWB

CHASSIS NO : VF37F9HF8FJ879163

ENGINE NO : 10JBFR0023433

REG. DATE : 2015

*Not Authorized
Penny Bpam*

4 days

Estimate Repair Cost to Vehicle No : GBE7515K

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Sliding door - RH	1	1,200.00	1,200.00
2 Sliding door protector - RH	1	185.00	185.00
3 Sliding door weatherstrip - RH	1	178.00	178.00
4 Sliding door centre roller - RH	1	350.00	350.00
5 Sliding door trimboard clips - RH	15	8.00	120.00
6 Rear fender - RH	1	1,200.00	1,200.00
7 Rear fender trimboard clips - RH	15	8.00	120.00
			3,353.00
		Add 10%	335.30
			3,688.30
SPECIAL NET			
8 Sliding door glass sealant	1	60.00	60.00
			60.00
LABOUR			
9 To remove and refit RH sliding door glass	1	60.00	60.00
10 To transfer RH damaged sliding door interior mechanism to new door	1	120.00	120.00
11 To panel beat and straighten RH sliding door pillar, RH rear fender inner panel, to cut and weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
12 To check and rectify wiring system	1	80.00	80.00
13 To putty and spray paint on affected areas	1	1,000.00	1,000.00
14 To supply and paste artwork on RH body panel	1	800.00	800.00
			3,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

interior mechanism to new

TOTAL S\$ 7,008.30

ADD GST @ 7% 490.58

GRAND TOTAL S\$ 7,498.88

SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED NINETY-EIGHT AND CENTS EIGHTY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/12/2020 11:03 (SGT)
Date of Accident	11/12/2020 19:21 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TEKKA CENTRE BASEMENT CARPARK B1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE7515K

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXXX78Z
Email Address	norazman.abdul_aziz@daimler.com
Mobile Phone No	(Phone) +65-88762075
Alternative Phone No	+65-88762075

VEHICLE PARTICULARS

Manufacturer	Peugeot
Model	PARTNER 1.6 HDI ETG LWB
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle


INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	999995580
Cover Note Number	-

DRIVER

Name of Driver	NUR HAKIM BIN GUL ZAMAN
NRIC No	SXXXX749E
Date Of Birth	26/06/1991
Occupation	Outdoor

SKETCH PLAN



Vehicle A: GBE7515K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

ACCIDENT STATEMENT (2000 characters)

My vehicle was stationary parked at B1 of TEKKA CENTRE as I parked too near to the pillar when I drove out I steered full right and therefore my vehicle right side collided onto concrete pillar. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

14 December 2020 at 2:02 PM

Date/Time:

14 December 2020 at 2:02 PM