

Venda Engineering & Trading Pte Ltd

Quotation

From:

VENDA ENGINEERING & TRADING PTE LTD

8 TUAS AVENUE 18 SINGAPORE 638892

Officer in Charge: SOON TAT NG

Tel: Email: Customer:

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD SINGAPORE 758123

Attn::

Tel: 6494 2800

Fax No.: 6861 7097

Quotation No.: CQO20-1210056	Quotation Date: 28/12/2020	Terms: 30 DAYS	
Vehicle No. : YP5081C	Chassis No.: FK62FMA30200	Policy Number :	
Model: FUSO FK62FMZ1RDEB		Date of Accident :	
Third Party Insurer :		TP Vehicle No. :	
Remarks:			

Remark	(e :					
Kemair						
ITEM	DESCRIPTION		Qty	UNIT PRICE	AMOUNT	(SGD)
	YP5081C					
1	ALUMINUM PLATE A		1	300.0000		300.00
2	SILICONE MA		2	60.0000		120.00
3	RIVET /		1.5	20.0000		30.00
4	COMPANY LOGO STICKER /-		1	450.0000	200	450.00
					,,,,	
5	REMOVE & RENEW REAR RIGHT CARGO BOX P	LATE	1	440.0000	300	440.00
6	SPRAY PAINT REAR CARGO BOX	Paru	1	300.0000	250	300.00
		434	4 •			
_		HP 9000	inold			
	LKK Auto Consultants hence notify the Repairer of the following:	2/2				
	To resurvey before/after spray painting	3 204	γ)			
l	To display damaged part(s) during resurvey Parts prices are subject to confirmation	119	I			
	Third party survey is on a "Without Prejudice" basis	~		Sub Total	1,	640.00
	No illegal modification(s) is allowed	29/12/2020		Discount		(0.00)
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	211.5		GST(7.00%) Total (SGD)		114.80 754.80
VENDA		(A (2A)			-	754.00
V LIVE	ENGLINE BUY ROBALT RADING PTE LTD Signature:	۸.	We accept	the above quotation	1.	
- 1	Date:	en after rep	4			
L	1/4	7				

Authorised Signature

Customer's Name & Signature Company Stamp/Date

Please conduct the survey at Venda Engineering @ 8 Tuas Avenue 18 Level 5 Singapore 638892

Mailing Address Contact Number (HQ)

: No.1, Sunview Road, #08-15 Eco-Tech@Sunview, Singapore 627615

: (Tel): 6355 9014 (Purchasing Dept.) 6355 9015 (Sales Dept.)

: venda_eng@singnet.com.sg









Page 1 of 1

(Fax): 6254 0424

CG000E / Aspectus Consultancy Pte Ltd W DATE & TIME: 16/12/2020 22:13 (SGT) ITED BY: Flash 1 MITTED B1. (16/12/2020 22:13 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- IMPORTANT NOTICE

 1. Please report correctly the details of the accident to speed up the claims process.

 2. This Form must be completed by the Policyholder and/or the Authorised Driver

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENTESTATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

16/12/2020 22:13 (SGT) 16/12/2020 11:30 (SGT) 55 Kim Chuan Rd, Singapore Precise Tree Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

YP5081C

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

Yes

GOLDBELL LEASING PTE LTD

1XXXXX196N

isaacngcl@gbl.com.sg

(Phone) +65-97237551

(Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Mitsubishi

Fuso

Employment

No - Claiming third party Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

MSIG

ThirdParty

Yes

29131844

DRIVER

Name of Driver

NRIC No

Date Of Birth Occupation

Muhammad Hafeez Bin Barmawi SXXXX221A 18/04/1988 Outdoor

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number **Email Address** Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

1 YEAR AND 2 MONTHS (Phone) +65-97237551

sheer.angullia@ninjavan.co Blk 850 Jurong West Street 81 #05-281

640850 No Hirer No

Dry

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collided into Parked Vehicle Clear

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

On 16.12.2020 at about 1130hrs, I parked my Veh A YP5081C at Precise Tree building loading bay. I then went to do my pick ups. And when I returned to my Veh A I saw Veh B YN8286U reversing with the tailgate opened. He was reversing into the lot on my right side of my vehicle. Veh B tailgate then scraped the middle portion. There were scratches, dents, and there was a hole caused by the tailgate. No one was injured.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes No No

EDETAILS OF OTHER VEHICLE PROPERTY IN

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver Passport No/FIN Contact Number Address

YN8286U Mitsubishi

Commercial vehicle

Narasimmanaidu Dhanasekaran

GXXXX164X

(Phone) +65-98921391

Accident report SA0G20CG000E

Page 2 of 21

7	
_{JSS} complement	
acode	-
surance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
No. 311 desertiget (melaunig 211VCI)	3

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to soned up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary
 investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as we'll as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Oriver's Signature (If driver is not the policyholder)

Date & Time.

(6.12.20 20 17 40hs Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Accident renor exposon

55 kim chuan Dring

A YP 5081 C B: YN 8286U



precise tree Building.

Coading Bay

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

THE ACCIDENT
On 16.12.2020 at about 1130 hrs 1 parked
my Veh A YP 5081 C at Preige Tree Building
lotiding bay. I then went todatick do my
pick ups. And when I returned to my veh A
Saw Veh BYN 82864 veversine with the
tail gote opened. He was veversing into the lot
on my right side of vehicle. Veh B tail gate
then scraped the middle portion. There were
scratches, dents and there was a hole caused by
the tailgate. No one was winsed.
DECLARATION
I/We declare the foregoing particulars are true in every respect
1.11.
Policyholder's Signature Driver's Signature Renning Centre Personnel's Signature
(If driver is not the policyholder) Name
Date & Time (6-12/2070
17401

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company		
Owner ID:	196N		
Vehicle No:	YP5081C		
Vehicle to be Exported:	No.		
Intended Deregistration Date:	29 Dec 2020		
Vehicle Make:	MITSUBISHI		
Vehicle Model:	FUSO FK62FMZ1RDEB		
Primary Colour:	White		
Manufacturing Year:	2016		
Engine No.:	6M60219380		
Chassis No.:	FK62FMA30200		
Maximum Power Output:			
Open Market Value:	\$61,602.00		
Original Registration Date:	02 Dec 2016		
First Registration Date:	02 Dec 2016		
Transfer Count:	0		
Actual ARF Paid:	\$3.081.00		
ettyntikije jaki sijani selentra eti eti (- mari be selentra selentra selentra s e			
PARF Eligibility:	No		
PARF Eligibility Expiry Date:			
PARF Rebate Amount:	\$0.00		
40000 (44) \$10000 (4000) (4000	ki saranda kurunun sepin saksi seni sehi aran dan direktaran sa sa sebah dian dian sembah dan bahasan karan da		
COE Expiry Date:	01 Dec 2026		
COE Category:	C - Goods Vehicle & Bus		
COE Períod(Years):	10		
PQP Paid:	\$24.847.00		
COE Rebate Amount:	\$14,714.00		
Total Rebate Amount: le information contained herein is correct as at 29 Dec 2020	\$14,714.00		

ок










White











II TUSO	rian'	rer F	K らつ
			NUZ
	. Watervoorst en	er aberratian	

Financial


Accessories

Similar

Research

Photos

Map



YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER



Price	\$68,800	Lifespan	31-May-2036
Depreciation ①	\$12,690 /yr View models with similar depre	Reg Date	01-Jun-2016 (5yrs 5mths 2days COE left)
Mileage	N.A.	Manufactured ②	2016
Road Tax 🔿	N.A.	Transmission	Manual
Dereg Value ②	\$2,556 as of today (change)	OMV ①	\$54,4 04
COE 🥎	\$4,715	ARF ()	\$2,721
Engine Cap	7,545 cc	No. of Owners	1
Curb Weight	5,340 kg		
Type of Vehicle	Truck		

Features

View specs of the Mitsubishi Fuso Canter (2015)



ASS. REC. BY: (CKAL) REF.	1960
ASSI	GNMENT
From: Date:	Veh No: 4 508 C Yr Regn; 2016/ DGC
Eslimated Cost:	Type: M.Car / M.Cycle / Bus / Van (Lorn) / Taxl / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MIV	Truck / Trailer or
To Inspect Vehicle No: YP 5081C	Make: MIDUBLAHH FUSOFK62FM . c.c 7545
at Workshop m/s VENBA ENGINEERING	Colour RGO A/C: Insured / Std / NI / NA
of No. 8, Thus ME 18	Sp.Reading
Insured: LONPAC	Eng/No:
Policy No.	C/No: FK62FMA 30200
Claims No.	Gen. Cond: Good Fals Poor / Burnt
Sum Insured: Excess:	Steering: Morder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Mil' S/Rim / STD A/Rim or
	Tyre Size: F: 245 70 R 19
(Policy Condition)	R: <u>u a</u>
Remark: The veh had commenced its N/S O/S	-41/1 = -1.
repair at the time of inspection.	TOYO / YOKO or AWSTONE
Bal. or Market Value: 75K	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm , R/Bal. 7/7 mm
GIA / PR Seen: Consistent? : Yes or No	UBal. 17 mm UBal. 77 mm
Est Repairs: days Res.: Yes or No	D.O.A. 16 (12/2020)
Lum Sum: % · 3 Val.: Yes or No	Survey held at UGNA
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / OS / N/S / U/C / Rooftop or
Vehicle: IN / C Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The 0/0 / Glassis Halle / Body Glastic and the state of t
fem (init - bok	
	•
Dale/Time, File Pass tu? : Prell. Report	Days Of Repair:
:i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
<u>2)</u> Add	Fee: : Site Insp (\$) _s+Rssi
	: Interview (\$) Photos
Reput Formal:	: Tech, Invs (\$) Ottises
Lump Sun / l.B.f: (\$)	:Weelend (\$
*	TOTAL