

12/12/2020

REF: CS3/SMO20014748/GUqd3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): GRACE TEO

of

SMO

Date/Time: 30/12/2020@4.01PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 7175B

Insured: FBN 7912A

at Workshop m/s AUTO BULLOX

Tel: 6844 4290

of 53 UBI AVENUE 1# 01-25

Policy No:

Claim No: CMTD2003843/AGC

Sum Insured:

Excess:

D.O.A. 22/12/2020

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 4.30PM@30/12/20

Person Contacted: ELMA

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	Repairer agreed to survey on 31/12/2020
	SLQ 7175B-X
	FBN 7912A-X