6d. CTi

ASSIGNMENT

Date:

Estimated Cost

O / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No

Workshop m/s Yong Sing Motor

Insured

Policy No

Claims No

Sum Insured Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Total or Market Value $58K

DAC Accident Report Consistent? : Yes or No

SIA / PR Seen. Consistent? : Yes or No

Est. Repairs 2 days Res.: Yes or No

Sum Sum 20 % 3 Val : Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date Person Contacted

Veh No: SKR 8641Y 1st Reg: 13 Mar 2015

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 218i c.c. 1499

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 77123 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA2A32070VZ50814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal	6 mm	R/Bal	6 mm
L/Bal	6 mm	L/Bal	6 mm

D.O.A: D.O.I: 4-01-21

Survey held at W/S 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CQE : 42536

Date/Time File Pass to:

Date/Time File Return to:

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp: (S

☐ Interview

Survey Fee:

Transportation