



Your Ref : MCT20100061

Date: 12th Jan 2021

Our Ref : CS3/III20011163/Qvd3e2-1

M/s India International Insurance Pte Ltd

64 Cecil Street
#05-02 IOB Building
Singapore 049711
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FW 9819D
INSURED VEHICLE SHA 4744K
ACCIDENT ON 03/10/2020**

Instruction was received to inspect the vehicle Reg. No. FW 9819D. The inspection was conducted on 15/10/2020 at the premises of M/s Hiap Lek Automobile Trading, 160 Sin Ming Drive, #05-17 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: FW 9819D
Make/Model	: Kawasaki KRR ZX150
Year of Registration	: 2003
Body Colour	: Silver
Chassis Number	: KR150KA57307
Engine Capacity	: 148 cc

The vehicle sustained damages at the n/s body and front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 3,500.00
Less: LTA Reimbursement Value (RV)	(S\$ 479.00)
Nett Liability	<u>S\$ 3,021.00</u> =====

Vehicle Inspected By:



OI SUN PIN

Asst. Automotive Assessor



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.