



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## AUTOMOBILE INSPECTION REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20014773/R1qd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 13-01-2021  
189556

Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | GBH 5054X      | <b>Veh. Inspected</b> | SHD 3156Z  |
| <b>Policy No.</b>   | 5101581770-02  | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | MT/1115685-002 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  |                | <b>Assign Date</b>    | 30/12/2020 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |          |
|-------------------------|-------------------|---------------------|----------|
| <b>Make &amp; Model</b> | HYUNDAI I40 1.7   | <b>c.c</b>          | 1685     |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2016     |
| <b>Chassis No.</b>      | KMHLB41UMGU091473 | <b>Colour</b>       | BLUE     |
| <b>Odometer</b>         | 473111            | <b>Steering</b>     | IN ORDER |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | NIL      |
| <b>General</b>          | FAIR              |                     |          |

### 3. Conditions of Tyres

|                       | Size       | Make     | Balance |
|-----------------------|------------|----------|---------|
| <b>R/H Front Tyre</b> | 205/60 R16 | DURATURN | 5 mm    |
| <b>L/H Front Tyre</b> | 205/60 R16 | DURATURN | 5 mm    |
| <b>R/H Rear Tyre</b>  | 205/60 R16 | DURATURN | 5 mm    |
| <b>L/H Rear Tyre</b>  | 205/60 R16 | DURATURN | 5 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |  |                        |            |
|-----------------------|--|------------------------|------------|
| <b>Accident Date</b>  | 30/12/2020   | <b>Inspection Date</b> | 30/12/2020 |
| <b>Survey held at</b> | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                        |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**