

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAI	L INSURANCE (S) PL	_	Ref:	CS/AGI20014801/Qvd3q2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE		Date:	28/01/2021	
				Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGS 268L	Veh. Inspected		SKN 8110J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008521/CH	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		31/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES C180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WDD1173422N082044	Colour		BLUE	
	Odometer	130374 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40 ZR18	MICHELIN		6 mm	
	L/H Front Tyre	225/40 ZR18	MICHELIN		6 mm	
	R/H Rear Tyre	225/40 ZR18	MICHELIN		6 mm	
	L/H Rear Tyre	225/40 ZR18	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	29/12/2020	Inspection Date	•	31/12/2020	
	Survey held at 60 JALAN LAM HUAT, #05-21					
	Repairer	MY CAR CONSULTANT PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: