



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S0M02ZK3
Reference	CS3/ASM20014805/Gqd3e2 
Loss Date	28 December 2020
Report Date	28 Dec 2020 1:54:00 PM
Request Date	31 December 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident SLX147S
Vehicle
Registration #

Make TPVD

Model OPEL

Service Address

’, ’

Primary Contact/Insured

ONG GECK LIAN
BLK 201D PUNGGOL FIELD, #05-278, 824201,
Singapore

JAS591662@GMAIL.COM

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Metrics

Notes



SERVICE REQUESTS

MESSAGES

CLAIMS

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2100084.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	7 January 2021
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	7 January 2021
 LKKPhoto.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 January 2021
 AXA Immediate Advice - SLX147S (PRS).pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 January 2021
 REPLY FROM TP.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	31 December 2020
 PRI TP EMAIL.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	30 December 2020
 PRI TP EMAIL PDF.pdf	Letters and Correspondence	Workshop	KUMAR Shailendra	30 December 2020

English (SG) ▼

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

SUB-TYPE

AUTHOR

DATE
UPLOADED



SERVICE REQUESTS

MESSAGES

CLAIMS

GIA Report

KUMAR Shailendra

30 December
2020

 [Insured GIA Report \(SME1495T\).pdf](#)

Reports & Statement

GIA Report

-

29 December
2020