

Our Job Ref No : 305440013

Date : 21.01.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHA7706B CTPL

19.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **FBR7651G**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount **\$875.02**
 - (b) Labour Charges **\$550.00**
 - Total for Part-By-Part Repair Cost** **\$1,425.02**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: **20%**
Final Lumpsum Repair cost

3. Estimated normal period for repairs: **2** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 27/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NTWL - CPP)
Date: 21.12.2020
Time: 10:44:11
Page: 1
LEE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440013
REGN NO : SHA7706B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 19.12.2020 09:00
ACCIDENT DATE : 19.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NO PLATE(S)	1	N	25.00	10.00	22.50	cra	✓	
0002 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1		459.40	20.00	367.52	cra	✓	
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1		451.25	20.00	361.00	cra	✓	
0004 09-01-0104-2133-G	IONIQVC ANTENNA ASSY-SMAR	1		40.50	20.00	32.40	?	Xnn	
0005 04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1		98.80	20.00	79.04	✓	nn	
0006 04-01-0104-2288-G	IONIQVC BEAM-RR BUMPER	1		394.80	20.00	315.84	?	Xnn	
0007 04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1		155.00	20.00	124.00	cra	✓	1065.65
0008 04-01-0104-2540-G	IONIQVC COVER-RR BPR UNDE	1		225.00	20.00	180.00	✓	Xnn	20% 852.52 sn 22.50
SUB-TOTAL :									1,482.30 875.02

JOB NATURE

Zowmf fee

0000 PB	PANEL BEATING	400.00	320	
0001 SP	SPRAYPAINT CHARGE	300.00	200	
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30	550

Tanpin 8244 5747

WP 21/12/20 C/pur

2 days hope

o/p Resury after repair paint
tanpin C/Handson

875.02

550

\$1425.02

2 days #

COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.12.2020

REPAIR ESTIMATE

Time: 12:39:32

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440013
REGN NO : SHA7706B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 19.12.2020 09:00
ACCIDENT DATE : 19.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NO PLATE(S)	1 N	25.00	10.00	22.50
0002 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00
0004 04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1 L	155.00	20.00	124.00

SUB-TOTAL : 875.02

JOB NATURE

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT CHARGE	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 550.00

TOTAL : 1,425.02

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :