

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

li min
Vehicle: IN / OUT
GalestarVeh No: SBS 8298G Yr Regn: 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or AMake: Scania c.c. _____Colour: Multi Colour A/C: Insured / Std / NI / NASp. Reading: 102 9948 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YS2K 4X2000 188137Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 275/70R22.5R: — (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 1/1

Rear

R/Bal. 8 8 mmL/Bal. 8 8 mmD.O.I. 4/1/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 No doc document given, will email over.

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____
\$ + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)