

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



GST Reg No : MR-8500111-X

/ WK SATURN BLACK

CR5 RUNWAY RED

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

Co Reg No : 199405410K **Owner Name & Vehicle Info Invoice Name & Address** Cust No/Name LCV07849/LIU WEILIANG, RYAN AIG Asia Pacific Insurance Pte. SMG8453H*ECB / 02/01/201 Reg No/Reg Date Itd. MOTOR CLAIM DEPARTMENT Date In/Mileage 78 SHENTON WAY #08-16 KNAF3416MK5023976 Chassis No AIG BUILDING Engine No G4FGJH713022 SINGAPORE 079120 KIA/CERATO 1.6 A EX G333 Make/Model Contact No 64191000

Colour/Trim

Credit	02/01/2021/ 10:38	0115					
		QUE	261 / Edwin Caina		26614		
	Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
							2000.00
R FLR PNL	, LHR FENDER & RHR	FENDER					2100.00
R RIMPER	RR FND PNL . BOOT	TITD . RR F	IR PNI . LHR FENDER	&			210010
	, IN END THE , DOOR	, , ,					
							120.00
REFIT BO	OTLID COMPONENT						120 0
	TID DOLDD TRIM A GO	LDDET					120.0
REFIT RR	FLR BOARD, IRIM & CA	AKPET F	7				30.00
RING FLEC	TRICAL SYSTEM			150			
VIIIO EEEO	THE STOPPEN	SIII)		120.0
OUT DIAG	NOSTIC CHECK USING	HI-SCAN PRO	TEST CL		7		
-SCAN PRO	TEST						50.0
NAMPED D	HATE HITH CACINO						50.00
K NMBEK P	LAIE WITH CASING						60.0
REFIT RE	VERSE SENSOR						
	· · · · · · · · · · · · · · · · · · ·						220.0
EVERSE SE	NSOR						00.0
							80.0
II CORROS	SION ON AFFECTED AREA	45					40.0
ar range							
AC DINDGE							20.0
							520.8
							192.8 15.2
							144.8
							165.6
	·DMO						254.4
	R FLR PNL RR BUMPER ER REFIT BO REFIT RR RING ELEC OUT DIAG SCAN PRO R NMBER P REFIT RE EVERSE SE TI CORROS &C BADGE BUMPER BUMPER L BUMPER F Y-SIDE T/	R FLR PNL , LHR FENDER & RHR RR BUMPER , RR END PNL , BOOTER REFIT BOOTLID COMPONENT REFIT RR FLR BOARD, TRIM & CA RING ELECTRICAL SYSTEM OUT DIAGNOSTIC CHECK USING -SCAN PRO TEST R NMBER PLATE WITH CASING REFIT REVERSE SENSOR EVERSE SENSOR TI CORROSION ON AFFECTED AREA &C BADGE BUMPER BUMPER BUMPER LWR BUMPER FOG LAMP, RH Y-SIDE T/SIGNAL, RH ING ASSY-BWS	REFIT BOOTLID COMPONENT REFIT RR FLR BOARD, TRIM & CARPET RING ELECTRICAL SYSTEM OUT DIAGNOSTIC CHECK USING HI-SCAN PRO- SCAN PRO TEST R NMBER PLATE WITH CASING REFIT REVERSE SENSOR EVERSE SENSOR TI CORROSION ON AFFECTED AREAS &C BADGE BUMPER BUMPER BUMPER LWR BUMPER FOG LAMP, RH Y-SIDE T/SIGNAL, RH ING ASSY-BWS	R FLR PNL , LHR FENDER & RHR FENDER RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER REFIT BOOTLID COMPONENT REFIT RR FLR BOARD, TRIM & CARPET RING ELECTRICAL SYSTEM OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST R NMBER PLATE WITH CASING REFIT REVERSE SENSOR EVERSE SENSOR TI CORROSION ON AFFECTED AREAS BC BADGE BUMPER BUMPER BUMPER LWR BUMPER FOG LAMP, RH Y-SIDE T/SIGNAL, RH ING ASSY-BWS	R FLR PNL , LHR FENDER & RHR FENDER RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & ER REFIT BOOTLID COMPONENT REFIT RR FLR BOARD, TRIM & CARPET RING ELECTRICAL SYSTEM OUT DIAGNOSTIC CHECK USING HI-SCAN PRD TEST R NMBER PLATE WITH CASING REFIT REVERSE SENSOR EVERSE SENSOR TI CORROSION ON AFFECTED AREAS &C BADGE BUMPER BUMPER LWR BUMPER LWR BUMPER FOG LAMP, RH 1.00 ING ASSY-BWS 1.00 1.00	REFIT REVERSE SENSOR TI CORROSION ON AFFECTED AREAS BUMPER BUMPER BUMPER BUMPER BUMPER BUMPER BUMPER BUMPER FOG LAMP, RH BUMPER FOG LAMP, RH 1.00 651.00 BUMPER GLAMP, RH 1.00 241.00 BUMPER FOG LAMP, RH 1.00 19.00 19.00 10.00	R FLR PNL , LHR FENDER & RHR FENDER RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & ER REFIT BOOTLID COMPONENT REFIT RR FLR BOARD, TRIM & CARPET RING ELECTRICAL SYSTEM OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST R NMBER PLATE WITH CASING REFIT REVERSE SENSOR EVERSE SENSOR II CORROSION ON AFFECTED AREAS BC BADGE BUMPER BUMPER 1.00 651.00 20.00 BUMPER FOG LAMP, RH 1.00 19.00 20.00 Y-SIDE T/SIGNAL, RH 1.00 181.00 20.00 ING ASSY-BWS 1.00 207.00 ING ASSY-BWS 1.00 ING A

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worπ or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



GST Reg No : MR-8500111-X

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	LCV07849/LIU WEILIANG, RYAN	
Ltd.	Reg No/Reg Date	SMG8453H*ECB / 02/01/201	
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0	
78 SHENTON WAY #08-16	Chassis No	KNAF3416MK5023976	
AIG BUILDING SINGAPORE 079120	Engine No	G4FGJH713022	
Contact No 64191000	Make/Mode1	KIA/CERATO 1.6 A EX G333	
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	02/01/2021/ 10:38	QUE	261 / Edwin Caina		26614		
		Description of Goods	s / Services			Unit Price		Amount
M STAY-RR					1.00		20.00	52.00 52.00
M STAY-RR					1.00 1.00		20.00	20.00
		BPR SIDE UPR,L BPR SIDE UPR,R			1.00		20.00	24.80
M PANEL AS		DIR SIDE OF NAME			1.00	324.00	20.00	259.20
M TRIM ASS	Y-RR TRAI				1.00		20.00	32.80
M PANEL AS					1.00 1.00	1297.00	20.00	1037.60 77.60
M HINGE AS M HINGE AS		-			1.00		20.00	77.60
M W/STRIP-					1.00	100.00	20.00	80.00
M LATCH AS			п]	1.00		20.00	89.60
M STRIKER		NK LID L	711	ima			20.00	32.00 25.60
M LOGO ASS M EMBLEM-C		B L	\mathfrak{I}		1.00		20.00	22.40
							l.	
		CHRVEVAR	NAME:					
		REMARKS						
Confirm &	accepted	by						
							tt	8,136.8 569.5
					7% GST on	8136.	80	207.3
					To	otal Payab	le	8,706.3

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident**

Additional Location Information

Country/State of Loss

02/01/2021 11:18 (SGT) 01/01/2021 16:43 (SGT) 6 Hoot Kiam Rd, Singapore 249393

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMG8453H

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address Mobile Phone No

Alternative Phone No.

No

LIU WEILIANG, RYAN

SXXXX659Z

RYAN87LIU@GMAIL.COM (Phone) +65-81275711

(Home) +65-81275711

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Kia

Cerato

Private use

Yes

Private car

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy Policy Number

Cover Note Number

AIG

Comprehensive

No

1800147027

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

LIU WEILIANG, RYAN

SXXXX659Z

06/01/1987 Indoor



Date Of Driving Pass Driving experience Gender Mobile Number

Alt. Phone Number Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Head to Rear Raining Wet

30/11/2005

Male

763342

Yes

No

Nο

No

Yes

3

No

2

15 YEARS AND 2 MONTHS

RYAN87LIU@GMAIL.COM

342C YISHUN RING ROAD #12-1944

(Phone) +65-81275711

(Home) +65-81275711

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

PASSENGER 1

Name Gender

PASSENGER 2

Name Gender PAMELA TAY

Female

GARETH LIU

Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?

If yes, against whom?

No

No

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes Yes

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model Vehicle Variant SHB6232C

-

-

Accident report SC1A21120001

Page 2 of 32

Vehicle Colour	Blue
Vehicle Category	Taxi
Name of Driver	SOON TECK MIN
Contact Number	(Phone) +65-96540217
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	COMFORT TAXI (BLUE)
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- $(v) \ complying \ w \ ith \ applicable \ law \ \ in \ administering, \ processing, \ handling \ and/or \ dealing \ w \ ith \ my \ claims.$

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

2/1/2021 9.15am

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Invell Bank Road

location of River Valley Rel

accident

River Valley Rel

Kim Seng Rel

Describe Circumstances of the Accident
While driving towards Great World shopping centre, approaching
the junction of Invell Bank Rd/ River Valley Rd / Rim Seng Rd.
I was on the 2nd lane from the right, the vehicle Kitront
of me made an emergency brake, the vehicle was a black lexus (SKG 946D). I was able to stop in time and there was
Lexus (SKG 946D). I was able to stop in time and there was
no contact with the black Lexus, However, after coming to
a stop, I was hit in the back by a blue comfort tax;
(SHB 6232 C). There was enough distance between my car and
the black lexus, so no impact has made with the cor
infront. The black Lexus moved off and sadid not stop to
assist with the accident.
Before the accident happened, I noticed a black SUV on
the extreme night lane, and the driver signalled night & was
going to turn right, but just after the junction, the driver
of the black Cur changed his signal & signalled left, he/she
of the black sur changed his signal & signalled left, he/she was on a turn right lane. There was a silver town infront
of the black Lexus, the taxi am brake due to the black SUV,
of the black Lexus, the taxi am brake due to the black SUV, this cause the black Lexus in front of me to jum on his brakes. As I had notice the black SUV trying to change lane,
brakes. As I had notice the black SUV trying to change lane,
I had applied my brakes early, however I had to jum on my
I had applied my brakes early, however I had to jum on my brukes when the black lesses stop aboutly. This could be
seen from the son board corners.
To and which is a set of
In my vehicle was my wife & 17 month old son at the buck seat, my con was in the child seat. There was a
passenger in the comfort taxi that lit me. No injuries were
is the scare The made were not due to be were
noticed at the scenew. The roads were vet due to heavy
Visite VIII Visite VIII Comments

Declaration


I/We declare the foregoing particulars are true in every respect.

02/01/2021 9.32am

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





Engine No.

COVER NOTE

LINE HOLD TO A STATE OF THE ST

KIA AUTO PROTECTOR PRIVATE VEHICLE

: G4FGJH713022

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : LIU WEILIANG, RYAN Period of Insurance : 02 Jan 2019 to 01 Jan 2021

Chasis No. : KNAF3416MK5023976 Vehicle No. Cover Note No.

Endorsement No.

Issued Date : 28 Dec 2018

ABOUT THE COVER

Make/Model : KIA Cerato

Engine Capacity/Tonnage: 1,591.00 CC Sum Insured : Market Value First Year of Registration : 2019 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") If You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has tess than 2

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under those headings.

EXCESS

Section 1 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

LIU WEILIANG, RYAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408850 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hottine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg. or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.

If We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Molassiya) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysla). For Corporate Posicies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504622210

C&CKICP2 - JAMES

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte, Ltd. **AUTHORISED REPRESENTATIVE**

5 No.201009404M | Copyright © 2016 AIG Asse Pacific Insurance Phe