


ASS. REC. BY: Stere REF: A14

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Sum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMG 8453H Yr Regn: 2/1/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Cerato c.c. 1591
Colour: Red A/C: Insured / Std / NI / N
Sp. Reading: 49808 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KNAE3416 MK 5023976
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front		Rear	
R/Bal.	<u>4</u> mm	R/Bal.	<u>4</u> mm
L/Bal.	<u>4</u> mm	L/Bal.	<u>4</u> mm
D.O.A.	<u>11/1/21</u>	D.O.I.	<u>4/1/21</u>

Survey held at Cycle & Carriage
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-69K</u>

Date/Time, File, Pass to? ☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

Rep/Forms:

Imp Sum / L.C. / C

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)	) S + RS, \$
☐ : Interview (\$ _____)	
☐ : Tech. Invs (\$ _____)	
☐ : Weekend (\$ _____)	

Survey Fee:

Transportation:

Photo

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV07849/LIU WEILIANG, RYAN Reg No/Reg Date SMG8453H*ECB / 02/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5023976 Engine No G4FGJH713022 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	02/01/2021/ 10:38	QUE	261 / Edwin Caina	26614		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , BOOTLID & RR END PNL REPAIR RR FLR PNL , LHR FENDER & RHR FENDER				400X2			800 2000.00
E PNT98000 RESPRAY RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & RHR FENDER				480 X 2 (CR5 colour)			960 2100.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT							120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET (PHOTO)							? 120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUPPLY RR NMBER PLATE WITH CASING							X 50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							60.00
M SUNDRY SUPPLY REVERSE SENSOR							? 220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40 80.00
M SUNDRY SUPPLY C&C BADGE							40.00
M SUNDRY Sundries							20.00
M COVER-RR BUMPER				1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR				1.00	241.00	20.00	192.80
M COVER-RR BUMPER FOG LAMP, RH				1.00	19.00	20.00	15.20
M LAMP ASSY-SIDE T/SIGNAL, RH				1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS				1.00	207.00	20.00	165.60
M BEAM-RR BUMPER				1.00	318.00	20.00	254.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV07849/LIU WEILIANG, RYAN Reg No/Reg Date SMG8453H*ECB / 02/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5023976 Engine No G4FGJH713022 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	02/01/2021/ 10:38	QUE	261 / Edwin Caina	26614			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	STAY-RR BUMPER LH				1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH				1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR,L	X			1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR,R	X			1.00	31.00	20.00	24.80
M	PANEL ASSY-BACK				1.00	324.00	20.00	259.20
M	TRIM ASSY-RR TRANSVERSE				1.00	41.00	20.00	32.80
M	PANEL ASSY-TRUNK LID	✓	QD		1.00	1297.00	20.00	1037.60
M	HINGE ASSY-TRUNK LID,LH	X			1.00	97.00	20.00	77.60
M	HINGE ASSY-TRUNK LID,RH	X			1.00	97.00	20.00	77.60
M	W/STRIP-TRUNK LID OPNG	X			1.00	100.00	20.00	80.00
M	LATCH ASSY-TRUNK LID	X			1.00	112.00	20.00	89.60
M	STRIKER ASSY-TRUNK LID	X			1.00	40.00	20.00	32.00
M	LOGO ASSY-KIA SUB	✓	PLC		1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	✓	PLC		1.00	28.00	20.00	22.40

Estimate

Estimate

SURVEYOR NAME: Steve CLKK 4/1/21, 10:39am
 SURVEYOR SIGNATURE: OO-NM AL
 DATE: EXCIS - ?
 REMARKS: P/P
Ry BIL SM
4 days

Confirm & accepted by
 LKK Auto Consultants hence notify
 Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental repairs must be resurveyed and
 Authorized signatory and company stamp

	Nett	8,136.80
7% GST on	8136.80	569.58
Total Payable		8,706.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

02/01/2021 11:18 (SGT)
01/01/2021 16:43 (SGT)
6 Hoot Kiam Rd, Singapore 249393
-
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMG8453H

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No
LIU WEILIANG, RYAN
SXXXX659Z
RYAN87LIU@GMAIL.COM
(Phone) +65-81275711
(Home) +65-81275711

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category

Kia
Cerato
-
Private use
Yes
Private car

INSURANCE COMPANY

Name of Insurance Company
Type of Coverage
Fleet Policy
Policy Number
Cover Note Number

AIG
Comprehensive
No
1800147027
-

DRIVER

Name of Driver
NRIC No
Date Of Birth
Occupation

LIU WEILIANG, RYAN
SXXXX659Z
06/01/1987
Indoor

Of Driving Pass
ing experience
nder
obile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

30/11/2005
15 YEARS AND 2 MONTHS
Male
(Phone) +65-81275711
(Home) +65-81275711
RYAN87LIU@GMAIL.COM
342C YISHUN RING ROAD #12-1944

-
763342
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Raining
Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
3
No

PASSENGER 1

Name
Gender

PAMELA TAY
Female

PASSENGER 2

Name
Gender

GARETH LIU
Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant

SHB6232C
-
-
-

Vehicle Colour
Vehicle Category
Name of Driver
Policy Number
Business
Business complement
Insurance code
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
Details Of Passenger (Including Driver)

Blue
Taxi
SOON TECK MIN
(Phone) +65-96540217
-
-
-
-
COMFORT TAXI (BLUE)
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


2/1/2021 9.15am

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

while driving towards Great World shopping centre, approaching the junction of Inwell Bank Rd / River Valley Rd / Kim Seng Rd. I was on the 2nd lane from the right, the vehicle in front of me made an emergency brake, the vehicle was a black Lexus (SKG 946D). I was able to stop in time and there was no contact with the black Lexus. However, after coming to a stop, I was hit in the back by a blue Comfort taxi (SHR 6232 C). There was enough distance between my car and the black Lexus, so no impact was made with the car in front. The black Lexus moved off and did not stop to assist with the accident.

Before the accident happened, I noticed a black SUV on the extreme right lane, and the driver signalled right & was going to turn right, but just after the junction, the driver of the black SUV changed his signal & signalled left. he/she was on a turn right lane. There was a silver taxi in front of the black Lexus, the taxi jam brake due to the black SUV, this cause the black Lexus in front of me to jam on his brakes. As I had notice the black SUV trying to change lane, I had applied my brakes early, however I had to jam on my brakes when the black Lexus stop abruptly. This could be seen from the on board camera.


In my vehicle was my wife & 17 month old son at the back seat, my son was in the child seat. There was a passenger in the comfort taxi that hit me. No injuries were noticed at the scene. The roads were wet due to heavy rain but vision was clear.

Declaration

We declare the foregoing particulars are true in every respect.


02/01/2021 9.32am
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : LIU WEILIANG, RYAN
Period of Insurance : 02 Jan 2019 to 01 Jan 2021
Engine No. : G4FGJH713022
Chasis No. : KNAF3416MK5023976

Vehicle No. : CMG 8453H
Cover Note No. : 1800147027
Endorsement No. :
Issued Date : 28 Dec 2018

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
LIU WEILIANG, RYAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278600

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504622210

C&CKICP2 - JAMES

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile
AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Jacintha Lin