ASP. REC. BY: Steve 1 AIG	ASSIGNMENT
	Veh No: SKU 3418T Yr Regn: 21/7/15
From: Date:	Type (M.Car / M.Cycle / Bus / Van / Lorry /.Text / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD TP/WS/JP RES/OD RES/EVA/INV/MY	Make: KIA Forte c.c. 15.91
To Inspect Vehicle No:	Colour B/48 A/C: Insured / Std / NI / N
al Workshop m/s	Sp.Reading ; 70673 T/Radio: Insured / Std / NI / N
ol	
Insured:	Eng/No: . VIII EXILL MIE CILL & LLG
Policy No.	C/No:
Claims No.	Gen. Cand: Good (Fa) / Poor / Burnt
Sum insured: Excess:	Steering: leorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerden/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / SKRim / STO ARIM or
3	Tyre Size: F: 908/55/16
	R: U
(Policy Condition)  Remark: The veh had commenced its  N/S' ' 'O/S	A TOTAL CONTRACTOR OF THE PARTY
repair at the time of inspection.	TOYOTYOKO OF CONTINUAL
repair of the diffe of mapourem	Pon
Sal. or Market Value:	- 1
IDAC Accident Rport: Consistent?: Yes or No	Noal, Similar
SIA / PR Seen: Consistent?: Yes or No	UBal. S mm
Est. Repairs: days Res.: Yes or No	D.O.A. 27/12/20 D.O.I. 4/1/21
Lum Sum: % 3 Val.: Yes or No	Survey held at CYCIE & CAMAGE
Loui Suit.	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	
Vehicle: IN / OU  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	
MV-45K	
: Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
ale/Tune, File Return to?	Transportation:
Add Fee	e: : Site Inap (\$)s + Rssi
	: Interview (\$ ) Protos
ormes :	: Tech. Invs (% . ) Others
ung Sun I.G.I: Co	: Weel and (#
,,, = 1, -,,, = 1, , , , , , , , , , , , , , , , ,	YOTAL
	COUNTY TO THE PROPERTY OF THE PARTY OF THE P



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

	ESTIMATE	GST Reg No 1 MK-8500111-X			
Co Reg No : 199405410K Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No	/EU TEIK LEONG  SKU3418T / 21/07/201  04/01/2021/ 0  KNAFX411MF5448649  G4FGFH776547  KIA/FORTE K3 1.6 A EX W/ LED & D.BR  D7U / WK			

Account No AX00000	Terms Credit	Date/Time Printed	CSE	Operator					
AX00000		04/01/2021/ 11:28	OUK	282 / Kevin Leong		26681			
	Credit	Description of Goods	•		Qty (	Jnit Price	Disc%	An	nount
DALTOGODO		Description of Goods	7 001 11000					400	1200.00
PNT88000	FRT RUMP!	ER, SUPPORT PANEL & A	FFECTED ARE	E <b>A</b>				-, -,	350.00
PNT98000									330.00
	RK ON FR	T BUMPER PANEL						1	120.0
PNT88000			500 54071 7	TATE DEDAID				1	
	INSTALL	RADIATOR, CONDENSER	FOR FACILI	IAIE KEPAIK				7	80.0
SUNDRY		040							
TO TOP UF	PAIRCON	GAS						1	30.0
54900099	DING & C	HASSIS ELECTRICAL SYS	STEM					1	
10000001			r	]	п _				120.0
TO CARRY	OUT DIA	GNOSTIC CHECKLUSING	FI-SCAN BRP		$\bigcirc$ 5i	<b>V</b>			
USING HI-	-SCAN PRO	O TEST	$\sim$	111111161		)			50.0
					G (C)				50.
	Y FRONT I	NUMBER PLATE WITH FRA	AME.					20	50.0
SUNDRY								1	•
SUNDRIES LAMP ASSY	V UEAD DI	4 / BR			1.00	1870.00	20.00		1496.
LAMP ASSI		- 00			1.00	1870.00			1496.
		NT END MODULE -			1.00	776.00	20.00		620.
RADIATOR	ASSY <sub>4</sub>	7			1.00	546.00	20.00		436.
BLOWER AS	Y22				1.00	606.00	20.00	)	484.
GUARD-AIR		•			1.00		20.00		15.
GUARD-AIR	R,LH	" BR ag			1.00		20.00		15.
COVER-FR		. 1/0			1.00		20.00		582.
GRILLE AS		HION .	NR		1.00		20.00		257.
		LICENSE PLATE	NV.		1.00		20.00		16. 43.
LIP ASSY					1.00		20.00		26.
STRIP AS		GRILLE, UPR 1			1.00 1.00		20.00		38.
		SUMPER A/INTAKE			1.00		20.00		83.
		SUMPER ENERGY ?			1.00		20.00		77.
M STIFFNER		^			1.00		20.00		104.
								1	
Confirm &	accepted	by							

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



#### **CYCLE & CARRIAGE KIA PTE LTD** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

#### **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/EU TEIK LEONG		
Ltd.	Reg No/Reg Date	SKU3418T / 21/07/201		
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Date In/Mileage	04/01/2021/ 0		
	Chassis No	KNAFX411MF5448649		
	Engine No	G4FGFH776547		
	Make/Model	KIA/FORTE K3 1.6 A EX W/ LED & D.BR		
	Colour/Trim	D7U / WK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	04/01/2021/ 11:28	QUK	282 / Kevin Leong		26681		
		Description of Goods	/ Services		Qty	Unit Price	Disc%	Amount
	FR BUMPE	PER () R SIDE MTG,LH / BR R SIDE MTG,RH / BR			1.00 1.00 1.00	13.00	20.00 20.00 20.00	328.00 10.40 10.40
M BRACKET- M LOGO ASS					1.00		20.00	40.80

# Estimate Steve (LKK) 00- Ald ALL 4/1/21, 12.00pm Ex cers - 7. M BL SN 3 dys LKK Auto Consultants hence notify

#### • To resurvey before/after spray painting . To display damaged part(s) during resurvey • Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis Confidentancept.edniby be resurveyed and is subject to final approval from Insurance Company Nett 8,184.80 572.94 Acknowledged by Repairer 7% GST on 8184.80

Authorized signatory and company stamp

the Repairer of the following:

Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

8,757.74

Total Payable

AM200S000R-03 AIG Asia Paorfic Insurance Pte Ltd (\$401200500007-03 AIG Asia Paoific Insurance ENTAY DATE & TIME 22:12/2020 17:56 (SGT) ENTAY DATE BY: Faranchand Varisha CERSION 4 (30 12:2020 12:59 (SGT))



## SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

ADDRIANT NOTTICE
Please report <u>corrector</u> the details of the accident to speed up the claims process
This Form must be <u>completed</u> by the Policyholder and/or the Authorised Duxer 2. This Form must be assigned by the controlled and enqualities as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate a information provided must be as truthful and enquate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

alog repetion.
The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. policy karshity

If the issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

Any false reporting may be referred to the Police for investigation.

This record will be to waided by the insurers of the GIA frecords Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and find copies of this report will for a fee the made available upon application by interested parties.

Ey the odgement of this report to the insurers, you freeby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

A THE MET MENT OF THE PARTY OF

Date of Submission Date of Accident Exact Location of Accident

Additional Location Information

Country/State of Loss

28/12/2020 17:56 (SGT) 27/12/2020 10:25 (SGT)

Singapore

PIE Thomson flyover

Singapore

## 

Vehicle Registration Number

**SKU3418T** 

INSUFERIOR CLICISTICSER

is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Atternative Phone No.

No

Eu Teik Leong

62508039B

gerardeu@hotmail.com

(Phone) +65-96461840

+65-96461840

VEHICL PARTICULARS

Manufacturer

Macde

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Kia

Forte

Yes Private car

MISTERNOE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

AIG

Comprehensive

No

2100421910-05

EXSVER

Name of Driver

NRIC No

Date Of Birth

Occupation

EU JUN WEN BENJAMIN

S8731646G

08/10/1987

Indoor

טוועות Pass nving experience 10/11/2008 12 YEARS AND 1 MONTH gender Mobile Number Male Alt. Phone Number (Phone) +65-92707091 Email Address NOEMAIL@AIG.COM Address Blk 670 Address complement #07-35 Woodlands Drive 71 Postcode 730670 Is the driver the policyholder? No If No. Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No 2 Number of vehicles involved in the accident No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 has the driver been approached by unknown person(s) soliciting offering accident claims assistance? No DASSELVER 1 JOHN TAN Name Male Gender DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIPICUMSTANCES OF ACCIDENT On the 27th of december 2020 at approximately 1025 am. I was driving along the Circumstances Of Accident R2000006896 PIE towards KPE near the thomson flyover travelling at normal speed. Just after the turn the car (SFT 5007Y) in front had stopped abruptly. I applied the emergency brake but did not manage to stop in time and collided with the rear of the car (SFT 5007Y). We later moved to a nearby location to exchange contact details. The car (SFT 5007Y) already has existing dents on the car boot. The damage was to the bumper of the third party car. I myself sustained damages to the front of my car (SKU 3418T) the front grill and the bonnet. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? Yes IER WEHICLE PROPERTY 1

Vehicle Registration Number


SFT5007Y

Accident report SA0120CS000R

Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-Private hire -(Phone) +65-92369578 ---

shift<sup>®</sup>



Name of Policyholder

: Eu Teik Leong

Period of Insurance

: 21 Jul 2020 To 20 Jul 2021

Engine No.

: G4FGFH776547

Chassis No.

: KNAFX411MF5448649

Vehicle No.

CHERRIFIED SERVICE

: SKU3418T : 2100421910-05

Policy No. Endorsement No.

Issued Date

: 08 Jul 2020

#### ABOUT THE COMER

Make/Model

: KIA FORTE K3 1.6 A EX

Engine Capacity/Tonnage: 1,591.00 CC

Sum Insured: Market Value

First Year of Registration : 2015

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder

by Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience

ge Condition

: 30 years old and above

mitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriags of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Eu Teik Leong - \$600 (Own Damage), \$600 (Flood Cover)

## PPROVED REPORTING GENTRES/AUTHORISED REPAIRERS

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000 5.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800 4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Atternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of insurance rolates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189). Part IV of the Road Transport Act, 1987 (Melaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Melaysia).

0500709284

CYCLE & CARRIAGE - WINYEO(KIA)

239 ALEXANDRA ROAD

SINGAPORE 159930 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBH\_EAPP