


<<

Service Request Details

Claim
SOM02ZH6

Reference
None 

Loss Date
December 25, 2020

Report Date
Dec 26, 2020 12:00:00 AM

Request Date
January 4, 2021

Due Date
January 4, 2022

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pre-Repair Survey

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
FBH4938C

Model
YAMHA

Service Address

, , ,

Primary Contact/Insured

KOH TAT MING (XU DAMING)
APT BLK 113D MCNAIR ROAD, #18-230, 325113, Singapore

EDDIEKTM@HOTMAIL.SG

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg


Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	 REPLY FROM TP2.msg
TYPE	Letters and Correspondence
SUB-TYPE	Solicitor / Advocate
AUTHOR	KUMAR Shailendra
DATE UPLOADED	January 4, 2021

NAME	 SGV7113M.pdf
TYPE	Reports & Statement

AUTHOR KUMAR Shailendra

DATE UPLOADED December 29, 2020

NAME  SLH8419P INS GIA.pdf

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR KUMAR Shailendra

DATE UPLOADED December 29, 2020

NAME  PRI TP EMAIL FROM SOLICITOR.msg

TYPE Legal

SUB-TYPE Others

AUTHOR KUMAR Shailendra

DATE UPLOADED December 29, 2020

NAME  FBH4938C TP GIA.pdf

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR KUMAR Shailendra

DATE UPLOADED December 29, 2020
