

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000057/R1QD3E2
Date: 29/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070169930
Claimant Vehicle No : FBJ2187E Insured Vehicle No : SKM9696J
Date of Loss: 24/12/2020 Nature of Claim: TP Claim No: 1631134037SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ2187E**
Make & Model: KTM 200 DUKE, 200cc Engine No: 0390624397
Reg. Date: 13/02/2014 (Man. Year: 2013) Chassis No: VBKJUC404DC008108
Colour: Multi-colour Odometer: 12242 km
Engine Capacity: 200 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 150/60-17
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/01/2021
Date Inspected: 12/01/2021 Inspected At: JI Powersports (HQ)
1 Soon Lee Street #05-53
Singapore 627605
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F	
2	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F	
3	1		*SLIDER RH	Scratched	0.00 F	*- F	
4	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >