

ASSIGNMENT

Estimated Cost
 (TP/WS/TP RES/OD RES/EVA/INV/MV)
 Inspect Vehicle No:
 Workshop m/s: 1 Stop Garage
 Insured:
 Policy No.
 Claims No.
 Insured:
 (Client's Record)
 Make of Vehl:
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Val. or Market Value: \$54k
 JAC: Accident Report Consistent? Yes or No
 SIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 7 days Res: Yes or No
 Num Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date Person Contacted Vehicle IN / OUT

N/S	O/S

Veh No: SKR25924 Reg: 24 Dec 2013
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Countryman
 Make: Mini Cooper S cc: 1598
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp Reading: Bobbφ T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WMMZC 32060WR 77344
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 225/45 R18 CHABILEA
 R: 11 (Continental)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. D.O.I. 07-01-21
 Survey held at: W/S 12pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COB: 44628
	\$3000 - \$4000
	Submit PRR Report

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: -

Adnl Fees: Site Insp: \$
 Interview: \$
 ...

Survey Fee:	
Transportation	
...	