

Date: 24 Dec 2013
 Insured: Countryman
 Make: Mini Cooper S
 Colour: Brown
 Sp Reading: 130664
 Eng/No: WMWZC32060WR 273 44
 C/No: WMWZC32060WR 273 44
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD Rim or
 Tyre Size: F: 25 (45 R18 CHAB (LEAD))
 R: 11 (Continental)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal: 6 mm
 L/Bal: 6 mm
 D.O.A.: 07-01-21
 Survey held at: W/S
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

ASSIGNMENT

Insured Cost: TP / WS / TP RES / OD RES / EVA / INV / MV
 Inspect Vehicle No: 1 Stop Garage
 Workshop n/s: 1 Stop Garage

Insured: Countryman
 Policy No: Countryman
 Claims No: Countryman
 Insured: Countryman
 (Client's Record)
 Make of Veh: Countryman

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Market Value: \$54k
 JAC Accident Report: Consistent? Yes or No
 PIA / PR Seen: Consistent? Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Sum Sum: % 3 Val: Yes or No

N/S	O/S

Date: 24 Dec 2013 Person Contacted: Countryman Vehicle IN / OUT: Countryman
 Date/Time: Countryman File Pass to: Countryman
 Date/Time: Countryman File Return to: Countryman

Action / Instruction:
COB: 40629
\$3000 - \$4000

Date/Time: Countryman File Pass to: Countryman
 : Preli. Report
 : Final Report

Days Of Repair: Countryman
 Resurvey No. of Trip: Countryman

Adnl Fees: Site Insp: \$
 Interview: \$
 Countryman

Survey Fee: Countryman
 Transportation: Countryman
 Countryman