

ASS. REC. BY: Tough

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP'
 Date: _____ Person Contacted: Alan Vehicle: IN / OUT

Veh No: SHC 62294 Yr Regn: 2014 Oct
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Lotus Optima C.C. 1685
 Colour: 8/ver A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KN9 GM 414M F5542431
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/60R16
 R: 205/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 31/12/20 D.O.I. 4/1/21
 Survey held at Preriver Taxi
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear.
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>Butting mech.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 15/1/21-Typist
 Rep. Format: Merimen
 Lump Sum / L.B./C: \$820

Days Of Repair: 2
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ - RS - SI	
Pieces	
Others	
TOTAL	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

4-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6229 H

1 pc	Rear bumper	\$	696.00 <i>Rx</i>
1 pc	Rear bumper side bracket o/s	\$	29.00 <i>X</i>
1 pc	Rear o/s wheel cover	\$	116.00 <i>X</i>
		\$	841.00
Less 10%		\$	84.10
		\$	756.90

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>X</i>
1 pc	Rear bumper top protector	\$	80.00 <i>X</i>
1 pc	Rear o/s fender sticker	\$	60.00 <i>not</i>
1 set	o/s door stickers	\$	100.00 <i>X</i>
1 set	o/s rocker panel garnish clips	\$	38.00 <i>X</i>
Sundry		\$	50.00 <i>X</i>
To check rear o/s wheel alightment		\$	80.00 <i>X</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 <i>30</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, rear o/s door, rear o/s rocker panel garnish, etc		\$	850.00 <i>300</i>
To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, rear o/s rocker panel garnish		\$	800.00 <i>400</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>30</i>
		\$	3,102.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taylhor 9749 5749
 WP 4/1/21 @ 520pm
 Resurvey after repair.
 Taylhor @ (LKK Auto Consultants)
 2 days

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	23 Oct 2014 / 08:59:12	Receipt No.:	AACCK001-AX239-141023-000005
Asset Type:	Vehicle	Transaction Amount:	\$63,308.00
Asset ID:	SHC6229H	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141023085912903869		

Vehicle No.: SHC6229H
 Vehicle Type: H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Scheme: Taxi (Company)
 First Registration Date: 23 Oct 2014
 Original Registration Date: 23 Oct 2014
 Vehicle Make: KIA
 Vehicle Model: OPTIMA 1.7(A) DIESEL
 Chassis No.: KNAGM414MF5542431
 Engine No.: D4FDEH311473
 Motor No.: -
 Trailer Chassis No.: -
 Propellant: Diesel
 Passenger Capacity: 4
 Engine Capacity: 1685
 Power Rating: -
 Unladen Weight: 1584
 Maximum Laden Weight: 2050
 Primary Color: Silver

Secondary Color: -
 Manufacturing Year: 2014
 Open Market Value: \$19,730.00
 Minimum PARF Benefit: \$7,338.00
 PARF Eligibility: Y
 No. of Transfer: 0
 Effective Ownership Date/Time: 23 Oct 2014 08:59:12
 COE No.: 2014102301001305H
 COE Expiry Date: 22 Oct 2022
 COE Bid Category: -
 Actual QP/PQP Paid Amount: \$50,938.00
 Lifespan Expiry Date: 22 Oct 2022
 Owner ID Type: Company