

FCI ASSIGNMENT

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop n/s TC Autodivinc

Insured:

Policy No.

Claims No

Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Actual or Market Value:

DAC Accident Report:

Consistent? : Yes or No

GA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted

STH9830B 14 Mar 2020

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Nissan Serena 1.2cc 1198

Colour

white

Insured / Std / NI / NA

Sp Reading

13161

Radio: Insured / Std / NI / NA

Eng/No

C/No

JNIEBAC 27.80000 101

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/60 R16

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal

8

mm

L/Bal

8

mm

D.O.A

D.O.I

04-01-21
11:45

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Preli. Report

Date/Time, File Return to?



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp. (\$



Interview (\$



Photo (\$



Other (\$

Survey Fee:

Transportation:

Site Insp. (\$

Interview (\$

Photo (\$

Other (\$