

ASS. REC. BY:

REF:

CC3/111 21000/13/R16a3

0461

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 9168Eat Workshop m/s PERFORMANCEof 303, ALEXANDRA RDInsured: 111

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 119K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 9168E Yr Regn: 2018 / NOVType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318I LEO NAV c.c. 1499Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 32940 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA8E 32060A 85 4220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRIM / STD A/Rim orTyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / AMC / OHTSU / PIR / SUMI /
TOYO / YOKO or .

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 02/01/2021 D.O.I. 18/01/2021Survey held at PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Unit - 6SK

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

04 JAN 2021

ESTIMATE

Estimate No. : b1 57098
Date Estimated : 04/01/2021
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ong William
742 Tampines Street 72
#10-100

Singapore 520742

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF9168E	WBA8E32060A554220	29/11/2018	318i	0

DESCRIPTION

Replace rear bumper include remove attachment etc and carry out necessary repairs

VALUE
~~850~~ 1,275.00

Painting rear bumper

~~934~~ 1,038.00

To check electrical wiring system and lighting at the rear section for proper function.

~~150~~ 177.00

Sundries

? 150.00

Total Labour 1: 2,640.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT ?

QTY PRIC VALUE

REAR BUMPER CENTRE GUIDE ?

1 73.05 73.05

REAR BUMPER CARRIER (ECE) ?

1 56.05 56.05

REAR BUMPER TOWING EYE COVER PRIMED ~~de~~ X

1 470.25 470.25

REAR BUMPER PANEL PRIMED (BASIS) ~~de~~

1 43.70 43.70

(S/L) LH PROTECTION FOIL ?

1 1,184.75 1,184.75

(S/L) RH PROTECTION FOIL ?

1 10.75 10.75

SET MOUNTING PDC/PMA SENSOR REAR ?

1 10.75 10.75

REAR LH REFLECTOR ?

1 67.65 67.65

REAR RH REFLECTOR ?

1 37.90 37.90

DECOUPLING RING PDC TORQUE CONVERTER ?

1 37.90 37.90

ULTRASONIC SENSOR BLACK ?

4 5.15 20.60

4 239.25 957.00

Total Parts : 2,970.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57098
Date Estimated : 04/01/2021
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF9168E	WBA8E32060A554220	29/11/2018	318i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>18/01/2021 12:00</u>	Excess S\$ _____
Surveyor's Name <u>Rafael</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	



Labour 1	:	2,640.00
Parts	:	2,970.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	392.72
Grand Total	:	6,003.07

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/01/2021 20:49 (SGT)
Date of Accident 02/01/2021 21:41 (SGT)
Exact Location of Accident 381 Lorong 1 Toa Payoh, Braddell MRT, Singapore 319758
Additional Location Information Along bradell road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMF9168E

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner ONG WILLIAM
NRIC No SXXXX046I
Email Address ongw@singnet.com.sg
Mobile Phone No (Phone) +65-88766658
Alternative Phone No (Home) +65-88766658

VEHICLE PARTICULARS

Manufacturer BMW
Model 318i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company ERGO
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPG20012561
Cover Note Number NA

DRIVER

Name of Driver ONG WILLIAM
NRIC No SXXXX046I
Date Of Birth 14/05/1970
Occupation Indoor

Year of Driving Pass	10/05/1989
Driving experience	31 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88766658
Alt. Phone Number	(Home) +65-88766658
Email Address	ongwm@singnet.com.sg
Address	520742 #10-100
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Cheryl ong
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I was driving along bradell rd. I slow down behind a police car who was assisting some road works. Suddenly, vehicle B hit against my rear. My rear was damaged. It was a chain collision of 4 vehicles.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	Sjr8880k
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	Mr kok
NRIC No	SXXXX360A
Contact Number	(Phone) +65-97299688
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	Sku4031t
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Mr ch'ng
NRIC No	SXXXX306Z
Contact Number	(Phone) +65-96473080
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	Sjn865d
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Chan min-fay
NRIC No	SXXXX693H
Contact Number	(Phone) +65-83224290
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SHARIL BIN SATAR
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PLAN


A-SMF 9168E

B-SJK 8880K

C-8441317

D-SN 865D

BRADLEY
RD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

ACCIDENT STATEMENT (2000 characters)

I was driving along bradell rd. I slow down behind a police car who was assisting some road works. Suddenly, vehicle B hit against my rear. My rear was damaged. It was a chain collision of 4 vehicles.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

3 January 2021 at 3:30 PM

Date/Time:

3 January 2021 at 3:30 PM


2 JAN 2021

21:41

BRADSELL ROAD

THE
ARENA

PUB
RECREATION
CLUB



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0461
Vehicle No.:	SMF9168E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2021
Vehicle Make:	B.M.W.
Vehicle Model:	318i LED NAV
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	31705483B38B15A
Chassis No.:	WBA8E32060A554220
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,544.00
Original Registration Date:	29 Nov 2018
First Registration Date:	29 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$38,962.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2028
PARF Rebate Amount:	\$29,221.00

Intended COE Rebate Details

COE Expiry Date:	28 Nov 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,101.00
COE Rebate Amount:	\$24,448.00
Total Rebate Amount:	\$53,669.00

The information contained herein is correct as at 18 Jan 2021

OK

Black



Merimen e-Claims



Used 2018 BMW 3 Series 318i fo



PARF/COE

com/used_cars/info.php?ID=953196&DL=2683

BMW 3 Series 318i

Overview

Financial

Accessories

Similar

Research

Photos

Map



PERFORMANCE PREMIUM SELECTION LIMITED

Price	\$118,800		
Depreciation ?	\$12,760 /yr View models with similar depre	Reg Date	30-Oct-2018 (7yrs 9mths 11days COE left)
Mileage	61,949 km (27.9k /yr)	Manufactured ?	2018
Road Tax ?	\$684 /yr	Transmission	Auto
Dereg Value ?	\$53,967 as of today (change)	OMV ?	\$33,544
COE ?	\$31,801	ARF ?	\$38,962
Engine Cap	1,499 cc	Power	100.0 kW (134 bhp)
Curb Weight ?	1,425 kg	No. of Owners ?	1
Type of Vehicle	Luxury Sedan		

Features

BMW 1.5L Twin Power Turbo Engine, 136bhp, 8speed. Auto Start/Stop, IDrive With Bluetooth, Driving Experience Control - Eco Pro, Normal Or Sports Mode. View specs of the BMW 318i

