Surveyor: NAZ | REF: AIG

ASSIGNMENT

Date:

Veh No: FBN 3111X | Yr Regn: 6 SEP 2018

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA XABRE | c.c: 150

Colour: SILVER | A/C: Insured / Std / Nil

T/Bulp: Insured / Std / Nil

Sp Reading:

Engine:

Chsi: MH3RG3710HK025617

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Gearbox / Jammed / Locked / Burnt or

Brake: Gearbox / Jammed / Leaked / Burnt or

Wheels: MR / SpRim / STD / WRim or

Tyre Size: F: 110/70 - R17

R: 130/60 - R17

BS / DUN / EXHOVA / GY / FS / LZA / MC / OHTSU / PIR / SUMI / TOYO / YOKO or ZENEOS

	Front	Rear
R/Bal	4 mm	4
L/Bal	- mm	-

D.O.A: 29/12/2020 | D.O.S: 6/1/2021

Survey Fee of: BIKE PRODUCTION

Dec. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Top U/C / Chassis frame / Body Structure / Nodes over or

L/S

Excess:

Estimated Cost:

Vehicle Type: PR / MS / TP RES / OD RES / EVA / INV / MV

Insured Vehicle No:

Workshop Info:

Supervisor:

Claim No:

Sum Insured:

Claim Record:

Vehicle Condition

Damage commenced on:

Repair at the time of Inspection:

N/S	O/S

Repair Location: 9K

Repair Report: Consistent? Yes or No

Consistent? Yes or No

Repair Time: 3 days | Res.: Yes or No

Labour: % | Val.: Yes or No

Repair / REP. / 24 HRS

Vehicle IN / OUT

Person Contacted:

Date	Action / Instruction
	COE Rebate $3,364.00
	Repair Limit $5K. Repairer informed

FINALIZED LUMP SUM REPAIR $3100.00 / 3 DAYS

(RED: 3707.90;54%)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Stand:

Fees:

Other:

Total:

Survey Report: ☐ Prelim. Report ☐ Final Report

Other Fees Claimed:

Add Fee: ☐ Site Insp $ ☐ Interview $ ☐ Tech. Invs $ ☐ Weekend $

Report Number:

Lump Sum: LBUL/S