

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305441435
 REGN NO : SHB6629S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 23.01.2020
 DATE/TIME IN : 29.12.2020 09:40
 ACCIDENT DATE : 29.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	Rp
0002 04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	10 L	22.00	20.00	17.60	new
0003 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00	NN
0004 04-01-0104-0576-G	IONIQVC PANEL ASSY-QUARTE	1 L	1,768.30	20.00	1,414.64	bt
0005 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1 N	15.00	2.00-	15.00	new
0006 04-01-0104-0596-G	IONIQVC PANEL ASSY-REAR D	1 L	1,789.90	20.00	1,431.92	bt
0007 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	2.00-	80.00	we
0008 03-01-0104-2137-G	IONIQV4 CAP ASSY-WHEEL HU	1 L	346.40	20.00	277.12	art - 20%
SUB-TOTAL :					3,653.80	SN-95

JOB NATURE

0000 L	PANEL BEATING	960.00	800
0001 23-502	SPRAYPAINT ON AFFECTED AREA	650.00	600
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	30

3236.28

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305441435
REGN NO : SHB6629S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 23.01.2020
DATE/TIME IN : 29.12.2020 09:4
ACCIDENT DATE : 29.12.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-02	TRANSFER OF DOOR REAR LH	120.00		60		
0004 20-08	ADJUST REAR WHEEL ALIGNMENT	80.00		✓	1570	
SUB-TOTAL						: 1,890.00

TOTAL : 5,543.80

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Tanpin 97445749
'WP' 29/12/20 @ 4pm
P/P Resurvey before permit
4 days
tanpin@lkk.com
Wish

3236.28
1570
\$4806.28
0 days. \$

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: