

12/17/2020

REF: CS/MSG21000171/d3

Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVEY BY:

Merimen From (Person): KATHERINE WONG of MSIG

Date/Time: 5/1/2021@3.56PM

Estimated Cost:

Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 4533A

Insured: SGR 4972R

at Workshop m/s

RICO 60 AUTO

Tel: 9187 8064

of 8 KAKI BUKIT AVE 4 # 02-24

Policy No: 1001308095

Claim No: 251623

Sum Insured:

Excess:

D.O.A. 03/01/2021

Make of Veh:  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 4.16PM@5/1/2021

Person Contacted:

SHANELLE

Vehicle  IN /  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate	Repairer arrange to survey on 03/12/2020
	SLU 4533A- NA/INC21000092/z4	DOA : 03/01/2021
	SGR 4972R- NA/INC21000092/z4	DOA : 03/01/2021