



Your Ref: S9M01N3C

Date: 19<sup>th</sup> Jan 2021

Our Ref: CS3/ASM19008536/Gpd3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Stacey Ng

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBC 9949P  
INSURED VEHICLE: GU 7252A  
ACCIDENT DATE: 09/05/2019**

We thank you for your instruction on 04/01/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBC 9949P from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement and Police Report of Vehicles GBC 9949P and GU 7252A.

Pre-Repair Inspection Date : 14/05/2019 at M/s N-51 Automotive PL, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBC 9949P
Make & Model	: Nissan Cabstar 3.0 5M/T ABS 2DR 2WD EURO 5
Year of Registration	: 2014
Chassis Number	: JN1SC2F24Z0855621
Engine Capacity	: 2953 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.