

# ASSIGNMENT

Estimated Cost

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop in/s Teamwork Garage

Insured:

Policy No.

Claims No.

Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value

JAC Accident Report

IA / PR Seen

Est Repairs

Sum Sum

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

☐

: Preli. Report

☐

: Final Report

Add Fee:

☐

Site Insp. / \$

☐

Interview / \$

☐

Photo / \$

☐

Other / \$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

3 - Post List

Other

Other

Vehicle

Type M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp Reading

Eng/No

C/No:

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

L/Bal

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal

L/Bal

D.O.I.

w/s

05.01.21 5pm

SLV5517K

03 Jan 2018

Mazda 2 1.5 cc 1496

Grey

95619

JM6DJ2HAA01200253

Good

In order

In order

Nil

185/60 R16

11

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val: Yes or No

8/6 days

20 %