



AIG-TP CLAIM
SURVEY: 11/01/21
LKK - STEVE

VEHICLE NO : SLM 3885

MODEL : KIA/CERATO K3 1.6 A EX

WIP : 26617

Material	:	\$	<u>4,340.80</u>
Labour	:	\$	<u>2,840.00</u>
Sub-Total	:	\$	<u>7,180.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>7,180.80</u>
GST 7%	:	\$	<u>502.66</u>
Grand Total	:	\$	<u>7,683.46</u>

Re-Finalise By/Date : Warry on 09/02/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS

* TP VEHICLE NO: GBJ9640S

* GIA search fee \$2.00

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LAM LEE LEE Reg No/Reg Date SLM3885H / 29/03/2017 Date In/Mileage 11/01/2021/ 63524 Chassis/Package KNAFX411MH5696965 Engine No G4FGGH667924 Make/Model KIA/CERATO K3 1.6 A EX Colour/Trim MST METAL STREAM / WK SATURN BLACK
11/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/02/2021/ 13:50	TLE	884 / Lauro Songcuan	26617
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER & BOOTLID, REPAIR REAR END PANEL		(800+400)		1200.00 ✓
E PNT98000	SPRAY REAR BUMPER & BOOTLID		(700+350)		1050.00 ✓
E PNT88000	REMOVE & REFIT BOOTLID COMPONENTS				120.00 ✓
E PNT88000	REMOVE & REFIT REAR FLOOR BOARD, TRIM & CARPET				120.00 ?
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00 ✓
A 10028901	USING HI-SCAN PRO TEST				
E PNT88000	REMOVE & REFIT REVERSE SENSOR				60.00 ✓
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY	SUPPLY BODY PANEL SEALANT				40.00 ✓
M SUNDRY	SUPPLY C&C BADGE				40.00 ✓
M SUNDRY	SUNDRIES				20.00 ✓
X COVER-RR BUMPER		1.00	688.00	20.00	550.40 ✓
X COVER-RR BUMPER,CTR		1.00	315.00	20.00	252.00 ✓
X BEAM-RR BUMPER		1.00	318.00	20.00	254.40 ?
X STAY-RR BUMPER LH		1.00	120.00	20.00	96.00 ?
X STAY-RR BUMPER RH		1.00	120.00	20.00	96.00 ?
X PANEL ASSY-TRUNK LID		1.00	1570.00	20.00	1256.00 ✓
X LOGO ASSY-KIA SUB		1.00	37.00	20.00	29.60 ✓
X EMBLEM-CERATO		1.00	35.00	20.00	28.00 ✓
X EMBLEM K3		1.00	15.00	20.00	12.00 ✓
X LAMP ASSY-REAR COMB INSIDE,LH		1.00	710.00	20.00	568.00 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 11/01/2021	Cust No/Name	/LAM LEE LEE
	Reg No/Reg Date	SLM3885H / 29/03/2017
	Date In/Mileage	11/01/2021/ 63524
	Chassis/Package	KNAFX411MH5696965
	Engine No	G4FGGH667924
	Make/Model	KIA/CERATO K3 1.6 A EX
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/02/2021/ 13:50	TLE	884 / Lauro Songcuan	26617

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LAMP ASSY-REAR COMB INSIDE,RH	1.00	710.00	20.00	568.00
X LAMP ASSY-REAR COMBINATION,LH	1.00	788.00	20.00	630.40
Z TEXT				
TP CLAIM AIG - GBJ9640S				
SURVEY: STEVE (LKK) 11.01.2021				
DOA: 01.01.2021				
04 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	4,340.80		Nett	7,180.80
Labour	2,700.00	7% GST on	7180.80	502.66
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	7,683.46
Sundry/Others	140.00			
Total(w/o GST)	7,180.80			

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CAR NO: SLM3885HWIP: 26617

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Beam RR Bumper	? / SUPP		<u>OK</u>	
2	RH Beam Beam Bracket stay	? / SUPP	<u>OK</u>	<u>OK</u>	<u>Steve</u>
3	LH Beam Bracket stay	? / SUPP		<u>OK</u>	<u>12/1/21</u>
4	LHR LAMP M55Y CLET ①	② / SUPP	<u>OK</u>	<u>OK</u>	
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8	Kinect rear panel	? / SUPP		<u>Repair</u>	
9	SPRINT rear panel	? / SUPP	<u>OK</u>	<u>OK</u>	
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	<u>12/1/21</u>	<u>Steve</u>
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATOSURVEYOR: STEVE



HOME

Online



CERATO/FORTE../2017/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



CLU



BCM



SJB

8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SJB	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0236

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0177

OS Ver.

Android 9

HOME
 Online

 CERATO/FORTE../2017/G 1.6 MPI..
 VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

CLU
 BCM
 SJB

8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SJB	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0236	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0177	OS Ver.	Android 9