

ASS. REC. BY:

REF:

AIG / 210002101K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKN1543P

Yr Regn:

05, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Trans

c.c.

1997

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

128371

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAL 33.7 00000'S

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/11/20

D.O.I.

19/1/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. SI

Fuel

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Notarised
 L1 Putty &
 Putty After Pain
 5 days



ESTIMATE TO REPAIR

SURVEYOR NAME	: Kenneth LKK
DATE OF SURVEY	: 19.01.21.
TIME OF SURVEY	:

VEHICLE NO. : SKN 1543 P
 MAKE : NISSAN
 MODEL : TEANA 2.0L CVT
 YEAR : 2013
 CHASSIS NO : MNTBBAL33Z0000015

DATE : 4-Jan-21
 DATE OF ACCIDENT : 17-Nov-20
 THIRD PARTY REF : SJS 6875 J / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper	Nett		\$ Bu 907.10	✓
1 pc	RH Rear bumper retainer	Nett		\$ Bu 55.10	✓
10 ps	Rear bumper clips	Nett	\$ 2.60	\$ Bu 26.00	✓
1 pc	RH Rear fender	Nett		\$ Bu 1,377.30	✓
1 pc	Rear wind screen moulding	Nett		\$ Bu 155.90	✓
				\$ 2,521.40	
	Less 10%			\$ 252.14	\$ 2,269.26
1 tube	Rear windscreen sealant	S.Nett		\$ Bu 40.00	✓
	To Putty & Spray Paint			\$ 500.00	4200
	To remove & refix rear windscreen glass			\$ 100.00	✓
	To Anti Rust			\$ 50.00	300
	Labour Charges			\$ 680.00	6000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2020 09:02
Date Of Accident	17/11/2020 13:00
Exact Location Of Accident	THOMSON ROAD BEFORE THE TURNING INTO NEWTON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN1543P
Insured/Policyholder	
Name Of Registered Owner	GINO FABIAN POE
NRIC No	S7588419B
Email Address	GINOPOE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98292530
Alternative Phone No	OFFICE-98292530

Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	KRISTIANA
NRIC No	S8176965F
Date Of Birth	31/07/1981
Occupation	INDOOR
Date Of Driving Pass	21/07/2015
Driving Experience	5 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98292530
Fax Number	
Contact Number	
EMail Address	JUST.KRIS@GMAIL.COM

Address 10 SURREY ROAD #03-02
Postcode 307748
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ
Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I was turning from Moulmein road to Thomson road. As I got onto Thomson road (straight road), a dark blue grey Toyota Car (license plate: SJS6875J) came from nowhere and bumped into my car's rear end (right side). It happened right in front of a road barrier (white and orange colour barriers) and the collision was witnessed by 2/3 construction workers. The dark blue grey Toyota car was driven by an elderly couple (likely to be in their 60s to 70s), male driver and a domestic helper sitting in the back seat. It's a busy junction with construction works all over. As I couldn't stop on that narrow 2-lane along Thomson road with traffic coming from behind, I turned into Newton Road to find a safe spot to park my car. Instead of following me, the elderly Toyota driver continued onto Thomson Road. The traffic light towards Newton road was turning green, it was about to rain and I was on my way to pick up my son from his primary school at Barker road. The elderly driver drove past me pretended as if nothing happened. I noticed the dent on the Toyota's front left but as the car was moving I could only manage to take a photo of the vehicle and the car plate number from behind. I couldn't pull over anywhere along Newton road so I went straight to my apartment at Surrey Road to assess the damage on my car and headed straight out again to pick up my son from school. After I picked up my son, I contacted the police hotline and a traffic police officer came by to my place at 10 Surrey road to take my report and the SD card from my dash camera.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: NOT PROVIDED
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS6875J
Vehicle Make/Model/Colour