

SmartOne Auto Pte. Ltd.
Co. Reg No: 201939368E
8 Kaki Bukit Avenue 4
#08-09 Premier @ Kaki Bukit
Singapore 415875
Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com

By Email &/ Fax

Date: 05/0/ 7/

To: AIG

Attn: Motor Claims Department

Re: Accident involving motor vehicle Nos. SML 8600Z and SMK 897S along Lower Delta Road towards Kampong Bahru Road on 04/01/2021

We refer to the above matter.

We are instructed by <u>Chow Hwei Yann</u> to notify you of a road traffic accident on <u>04/01/2021</u> at about <u>17:05</u> at/along <u>Lower Delta Road</u> to wards <u>Kampong Bahru Road</u> involving our client's / customer's vehicle registration number <u>SML 8600 Z</u> and vehicle registration number <u>SMK 897S</u> (your insured) at the material time.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Thank You.

Yours faithfully,

Michelle

Hp: 9856 4815