

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

06TH JANUARY 2020

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP Ergo.
Denise.

Accident date: 03th JAN 2020

Estimated repair cost for vehicle no: SLH9072Z TOYOTA COROLLA ALTIS 1.6 (A)

S/n	Qty	Items	U/price	Amount
1	1	Front headlamp -RH		\$950.00
2	1	Front grille		\$0.00
3	1	Front grille emble logo		\$0.00
4	1	Front bumper		\$452.00
5	2	Front Bumper Side Bracket	\$85.00	\$170.00
6	8	Front bumper clips	\$12.90	\$103.20
7	1	Front fender -RH		\$412.20
8	1	Front fender cowling-RH		\$153.20
9	8	Front fender cowling clips-RH	\$12.90	\$103.20
10	1	Front R/H Door		\$1,050.10
11	1	Front outer handle -RH		\$155.30
12	1	Front R/H Door Protector-lower		\$161.40
13	1	Front R/H Door protector Molding		\$123.05
14	1	Front R/H Door Inner Lock		\$289.90
15	1	Front R/H Door Inner Trim Board		\$551.20
16	1	Front side skirt		\$551.00
17	1	Front R/H Door Inner Gear Motor Assy		\$372.40
18	1	Front tyre-RH		\$250.00
19	1	Front sport rim-RH		\$350.00
20	1	Front shock absorber-RH		\$312.00
21	1	Front knuckle arm-RH		\$268.10
22	1	Front lower arm-RH		\$255.10
23	1	Front wheel bearing-RH		\$168.20

Subtotal :- \$5,598.15

2286.65

1714.98

Labour charges

To remove & refit cushion

\$120.00 X

To remove & refit front & RH door gear motor glass

\$200.00 80

To remove & refit R/H front undercarriage

\$250.00 60

To check wheel alignment computer

\$150.00 80

To check wiring

\$60.00 30

Wheel alignment (computer)

\$150.00 X

Tuff kote

1080
\$120.00 30

Towing Fee

\$100.00 X

Panel beating

\$800.00 400

Spray painting

\$800.00 400

Subtotal :- \$2,750.00

Total:- \$8,348.15

total: 2754.98

L/s: 2.2K.

24 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: