

bul.
PRS

CTI

t

ASSIGNMENT

Estimated Cost:
TP / WS / TP RES / OD RES / EVA / INV / MV
Inspect Vehicle No:
Workshop m/s Chengchuam Motor
Insured:
Policy No.
Claims No.
Insured:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

al. or Market Value: \$110k
DAC Accident Report: Consistent? Yes or No
IA / PR Seen: Consistent? Yes or No
Est. Repairs: 6 days Res.: Yes or No
Sum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Veh No: SLQ33Z Regn: 18 Dec 2015
Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Vellfire
Colour: white A/C: Insured / Std / NI / NA
Sp Reading: 153441 T/Radio: Insured / Std / NI / NA
Eng/No: AGH 300029834
C/No:
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/50ZR18
R: 1/
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or King Kinforest
Front: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: ab-01-21
Survey held at: N/S 6pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$7000 - \$8000 (Repair Range)

Submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

3-PS

Food:

Other:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Test (\$

☐ Road Test