



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: SERENE LIM

Ref: CS/INC21000250/Uvd3q2

Date: 26/01/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 4887R	Veh. Inspected	SLX 6729Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1116072-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	06/01/2021

### 2. Vehicle Particulars & Condition

Make & Model	HONDA GRACE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GM61100541	Colour	BLACK
Odometer	71279 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	6 mm
L/H Front Tyre	205/50 R16	FALKEN	6 mm
R/H Rear Tyre	205/50 R16	FALKEN	6 mm
L/H Rear Tyre	205/50 R16	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	28/12/2020	Inspect Date / Time	06/01/2021 ( 09:56 AM )
Survey held at	15 KAKI BUKIT ROAD 4# 01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------