

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 31.12.2020

Time: 08:18:25

Page: 1

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

NTUC - C/P
 LKK-Taufik.

JOB NO : 305445434
 REGN NO : SHD6989S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 30.09.2020
 DATE/TIME IN : 30.12.2020 12:20
 ACCIDENT DATE : 30.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

PART REQUISITION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0104-2534-G FRT BUMPER	1	430.90	20.00	344.72	am
0002 04-01-0104-3818-G FRT BUMPER BRKT LH	1	28.00	20.00	22.40	X am
0003 04-01-0104-0632-G FRT BUMPER MOULDING LH	1	93.60	20.00	74.88	and / 524.50
0004 04-01-0104-4891-G DAY RUNNING LIGHT LH	1	642.50	20.00	514.00	X am - 20% - 419.60

SUB-TOTAL : 956.00

JOB NATURE

0000 PB PANEL BEATING
 0001 SP SPRAYPAINT CHARGE
 0002 17-01 CHECK ALL LIGHTING

350.00 320
 250.00 200
 40.00 30 550

SUB-TOTAL : 640.00

TOTAL : 1,596.00

\$969.60
 2 days #

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 92495747
 4/1/21 10am
 2 days

P/P Resurvey before paint
 Taufik E. Lkhantson