ASS. REC. BY: Taufth REF: ((4/191621000274/T1993

ASSI	GNN	TEI	TV

From: Date:	Veh No: SLF 3232 Dyr Regn: 2 0201 Jan.
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Vellfine - c.c 2493.
at Workshop m/s	Colour Klack A/C: Insured / Std / NI / NA
of	Sp.Reading / T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: 46H 300237653.
Claims No.	Gen. Cond: Good/Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / \$/Rim / STD A/Rim of
X	Tyre Size: F: 235/50/68
(Policy Condition)	R: 4 4 .
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TÓYÓ/YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Balmm , R/Balmm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 6/1/21
Lum Sum: % 3 Val.: Yes or No	Survey held at HP Huto
CA / REV / REP. / 24 HRS	Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The O/O / Ghassis frame / Body Structure allected due to composit.
- Potent med dedet	
District Constant	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fe	
Dan & Faussein	:Interview (\$) Photos
Report formal:	:Tech. Invs (\$) Others
Lump Sum / LEd: (F)	: Weelfend (\$)
	TOTAL



AP AUTOMOTIVE SERVICES PTE LTD ROC: 202022890H BLOCK 9006 TAMPINES STREET 93 #01-202 SINGAPORE 528840 TEL: 6784 4465 FAX: 6787 4886

Estimation

Date

Vehicle

SLF 3232 D

Make/Model

TOYOTA VELLFIRE

Chassis No.

AGH300237653

No.	Description	Unit	ι	Jnit Price		Amount
	Parts Replacment					
1	BONNET	1	\$	572.50	\$	× 572.50
2	BONNET CHROME	1	\$	462.85	\$	X 462.85
3	BONNET LOCK	1	\$	176.50	\$	X 176.50
4	BONNET HINGE L+R	2	\$	65.95	\$	x 131.90
5	HEAD LAMP L+R	2	\$	5,845.75	\$	XLH RH-UM/11,691.50
6	HEAD LAMP GARNISH L+R	2	\$	103.12	\$	
7	HEAD LAMP LOWER BRACKET L+R	2	\$	275.20	\$ (Ca 550.40
8	FRONT GRILLE ASSY	1	\$	1,241.90	\$	cm 1,241.90
9	FRONT GRILLE LOGO - TOYOTA	1	\$	1,091.65	\$	* CM / 1,091.65
10	FRONT GRILLE LOGO RADAR	1	\$	2,125.76	\$)	2,125.76
11	FRONT FENDER COWLING RH	1	\$	221.15	\$	× 221.15
12	FRONT BUMPER	1	\$	1,468.45	\$	tn 1,468.45
13	FRONT BUMPER GRILLE	1	\$	213.60	\$	de ~ 213.60
14	FRONT BUMPER FOGLAMP L+R	2	\$	521.70	\$	X 1,043.40
15	FRONT BUMPER FOGLAMP GARNISH WITH CHROME L+R	2	\$	677.32	\$4	!HX,RHde~ 1,354.64
16	FRONT BUMPER SENSOR SET	2	\$	397.85	\$	2 Hart ~ R4X 795.70
17	FRONT BUMPER RETAINER L+R	2	\$	67.70	\$	人 135.40
18	FRONT BUMPER REINFORCEMENT BAR	1	\$	352.89	\$	K 352.89
19	FRONT BUMPER SPONGE	1	\$	90.45	\$	de ~ 90.45
20	WIPER WASHER TANK	1	\$	142.65	\$	× 142.65
21	FRONT SUPPORT PANEL	1	\$	1,189.78	\$	X 1,189.78
22	FRONT SUPPORT PANEL TOP GARNISH	1	\$	245.95	\$	× 245.95
23	AIRCON CONDENSOR AIRGUIDE L+R	12	\$	89.62	\$	de 179.24
	Brace panel btv			Total	\$	25,684.50
	/			Less 25%	\$	6,421.13
				Total	\$	19,263.38

	S/Nett Items				
1	FRONT BUMPER CLIPS SET	1	\$ 100.00	\$ 30 rec	100.00
2	FRONT FENDER COWLING CLIPS SET	1	\$ 200.00	\$ ×	200.00
3	FRONT SUPPORT TOP GARNISH CLIPS SET	1	\$ 100.00	\$ ×	100.00
4	FRONT CAMERA	1	\$ 900.00	\$ ×	900.00
			Total	\$	1,300.00

LABOUR			
--------	--	--	--

	Total Amount For Labour					10,950.00
	Parts Replacement Amount					20,563.38
			Total	\$		10,950.00
10	TO RNR FRONT CAMERA AND TEST FUNCTION	1	600	\$	30.	600.00
	TO PERFORM RUST PROOFING	1	600	\$	X	600.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	1200	\$	150.	1,200.00
7	TO CHECK WATER LEAK	1	150	\$	X	150.00
6	TO UNLOAD AND RNR UPHOISTERY	1	1200	\$	X	1,200.00
5	TO RNR FRONT LOGO RADAR AND TEST FUNCTION	1	600	\$	150	600.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$	30	150.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$	30.	150.00
2	PANEL BEATING ON AFFECTED AREAS	1	3600	\$	400.	3,600.00
1	SPRAY PAINT ON AFFECTED AREAS	1	2700	\$	400	2,700.00

Taufth 97495749

WP 6/1/21@ 1700 04 days
i/5 & Resum affer repair of tarphin @ / Manks. com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is an a "Without Prejudice" basis

31,513.38

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total Amount

Date:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information

Country/State of Loss

04/01/2021 18:32 (SGT) 31/12/2020 18:00 (SGT)

333A Orchard Rd, Singapore 238897

MANDARIN GALLERY FEXIT B4 GRANGE RD

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLF3232D

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No **Email Address** Mobile Phone No

Alternative Phone No

No

JONATHAN TAN 7HI YING

SXXXX898F jt97jt@gmail.com (Phone) +65-93265115

+65-93265115

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Toyota

Vellfire

Private hire

No - Claiming third party

Private hire

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

NTUC

Comprehensive

No

5115692133

DRIVER

Name of Driver

NRIC No

Date Of Birth Occupation

JONATHAN TAN ZHI YING

SXXXX898F 08/04/1994 Outdoor

Date Of Driving Pass Driving experience

Gender Mobile Number

Alt. Phone Number **Email Address** Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance? Was any other material or property damaged?

Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE ATTACHED STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

08/01/2013

7 YEARS AND 11 MONTHS

Male

(Phone) +65-93265115

+65-93265115

jt97jt@gmail.com

BLK 537 SERANGOON NORTH AVE 4

#08-161 550537

Yes

No

Collision - Head to Rear

Raining Wet

No

2 Yes

No Yes

1

No

No

No

SJQ1368A

Private car

Accident report SN082114000D

Page 2 of 14

Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person

Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?

JONATHAN TAN ZHI YING

ADDRESS SHIP YING

NECK & BACK
SLF3232D

Yes

No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, nvestigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

16+6-6

Policyholder's Signature Date & Time:

16166

Driver's Signature (If driver is not the policyholder)

Date & Time

04/01/21 Reporting Centre Personnel's Signature

NRIC/FIN No.

SKETCH PLAN

MANDARIN GALLERY EXT BEFORE GRANGE RD.

VEH.A-SLF3	23217	
VEH.B-SJQ13		ANGE ROAD
DESCRIBE CIRCUMSTANC	/	
ON THE	STATED DATE A	NO TIME. I, VGH. A
WAS STA	TIONARY ON THE	E STATED VENUE.
		WERSE AND BANG
onto my	VEHICLE FROM	1 portion.
ECLARATION We declare the foregoing part	iculars are true in every respect.	
1466	JULL-L	olym ouls be
olicyholder's Signature ate & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 898F

Vehicle Details

Vehicle No.: SLF3232D

Vehicle to be Exported:

Intended Deregistration Date: 31 Jan 2021

Vehicle Make: TOYOTA

Vehicle Model: VELLFIRE 2.5ZG CVT

Primary Colour: Black

Manufacturing Year: 2019

Engine No.: 2ARJ253230 Chassis No.: AGH300237653

Maximum Power Output: 134.0 kW (179 bhp)

Open Market Value: \$50,385.00
Original Registration Date: 23 Jan 2020

First Registration Date: 23 Jan 2020

Transfer Count: 0

Actual ARF Paid: \$62,693.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Jan 2030 PARF Rebate Amount: \$47,019.00

Intended COE Rebate Details

COE Expiry Date: 22 Jan 2030

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$42,020.00

COE Rebate Amount: \$37,523.00

Total Rebate Amount: \$84,542.00

The information contained herein is correct as at 04 Jan 2021

ОК