Official CBR Page 1 of 2

## **Certification for Bus Repairs**

SBS Transit

CBR REF NO.: AM20203510

 Depot :
 AM
 Report No.: <u>E35002020</u>
 BUS VEHICLE NO. : <u>SBS8429X</u>

Driver's Co no. & Name : 13297 Phua Heng Yong

**Accident Date :** <u>06/09/2020</u>

**Date in :** 06/09/2020 **Date Out :** 10/09/2020

Yr Of Reg	Make / Model	Chassis No.		
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001862234		

Sto	Description	Quantity	Total Material cost (S\$)	
		0		\$0.00
		TOTAL FOR PARTS	S\$	-
S/N	Labour / Spray Painting / Contractor	Cost	А	mount
1	(2) Workshop Labour		S\$	192.00
2	Contractor's repair charges		S\$	550.00
	TOTAL LABOUR / SPRAY PAINTIN	IG / CONTRACTOR COST	S\$	742.00
	Repair cost of	Advertisement / Livery	S\$	585.00
		TOTAL DAMAGE	S\$	1327.00

Official CBR Page 2 of 2

## **Certification for Bus Repairs**

SBS Transit CBR REF NO.: AM20203510

**Depot:** AM Report No.: E35002020 BUS VEHICLE NO.: SBS8429X

**Driver's Co no. & Name :** 13297 Phua Heng Yong

**Accident Date :** 06/09/2020

**Date in :** 06/09/2020 **Date Out :** 10/09/2020

Yr Of Reg	Mak	e / Model	Chassis No.			
2008	Scania KUB4	X2, SD, AC, 2 Axle	YS2K4X20001862234			
			TOTAL DAMAGE		S\$	1327.00
			Overheads		S\$	222.60
			Towing Charges		S\$	-
Repair Period: 1 day(s)			Loss of Use		S\$	356.29
			TOTAL LOSS		S\$	1905.89

**Prepared By :** <u>Li Ming</u> **Date :** <u>14/09/2020</u>

Approved By

Workshop Mgr: Wong Yew Fatt

Date: 14/09/2020

Survey Fee	refer to Group	Claims
TOTAL DUE	S\$	1905.89

**Acknowledged By** 

Depot Safety: Chang Su Peng

Date: 14/09/2020

<sup>\*</sup> This is computer generated document and does not require signature