

## Certification for Bus Repairs

CBR REF NO. : AM20203510Depot : AMReport No.: E35002020BUS VEHICLE NO. : SBS8429XDriver's Co no. & Name : 13297 Phua Heng YongAccident Date : 06/09/2020Date in : 06/09/2020Date Out : 10/09/2020

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001862234

Stock Code	Description	Quantity	Total Material cost (S\$)
		0	\$0.00
<b>TOTAL FOR PARTS</b>			<b>S\$ -</b>
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	192.00
2	Contractor's repair charges	S\$	550.00
<b>TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST</b>			<b>S\$ 742.00</b>
<b>Repair cost of Advertisement / Livery</b>			<b>S\$ 585.00</b>
<b>TOTAL DAMAGE</b>			<b>S\$ 1327.00</b>

742  
 585  


---

 1,327

COR  
 \$ 1,327

1 days

## Certification for Bus Repairs

CBR REF NO. : AM20203510Depot : AMReport No.: E35002020BUS VEHICLE NO. : SBS8429XDriver's Co no. & Name : 13297 Phua Heng YongAccident Date : 06/09/2020Date in : 06/09/2020Date Out : 10/09/2020

Yr Of Reg	Make / Model	Chassis No.
2008	Scania KUB4X2, SD, AC, 2 Axle	YS2K4X20001862234
<b>TOTAL DAMAGE</b>		<b>S\$ 1327.00</b>
<b>Overheads</b>		<b>S\$ 222.60</b> X
<b>Towing Charges</b>		<b>S\$ -</b>
<b>Repair Period : 1</b> day(s)	<b>Loss of Use</b>	<b>S\$ 356.29</b> X
<b>TOTAL LOSS</b>		<b>S\$ 1905.89</b>

Prepared By : Li MingDate : 14/09/2020Approved By  
Workshop Mgr : Wong Yew FattDate : 14/09/2020

	Survey Fee	refer to Group Claims
<b>TOTAL DUE</b>	<b>S\$</b>	<b>1905.89</b>

Acknowledged By  
Depot Safety : Chang Su PengDate : 14/09/2020

\* This is computer generated document and does not require signature