ASS. REC. BY: Sun Pin REF: AIG			
——————————————————————————————————————	GNMENT		
From: Date:	Veh No: 5BS 8429 × Yr Regn: /200	08	
Estimated Cost:	Type: M.Car / M.Cycle Bus Yan / Lorry / Taxi / Prime Mover /		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Scania c.c 8867	7 .	
at Workshop m/s	Colour Multicolour A/C: Insured / Std / NI / N	NA	
of	Sp.Reading 10/3412 T/Radio: Insured / Std / NI /	NA	
Insured:	Eng/No:		
Policy No.	C/No: YS2K4X 2000 1862234		
Claims No.	Gen. Cond: Good Fair / Poor / Burnt		
Sum Insured: Excess:	Steering: horder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or		
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or		
	Tyre Size: F: 275/70 R22.5		
(Policy Condition)	R: 275 / 70 R22.5		
Remark: The veh had commenced its N/S O/S DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SU			
repair at the time of inspection.	TOYO/YOKO or		
Bal. or Market Value:	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No		mm	
GIA / PR Seen: Consistent?: Yes or No		mm	
Est. Repairs:days Res.: Yes or No	D.O.A. 06/09/2020 D.O.I. 10/09/2020	,	
Lum Sum: % 3 Val.: Yes or No	Survey held at SBS Transit.	В	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S N/S / U/C / Rooftop or		
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to colli	ision.	
Date / Time Action / Instruction			
	Repair day - 20	days	
		U	
		2	
	20		
:			
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 1	5	
CONTRACTOR OF THE PARTY OF THE	Resurvey No. of Trip: Survey Fee:		
1) ; Final Report Date/Time, File Return to?	Transportation:		
2) 11/1/21-Typist Add Fee			
	: Interview (\$) Photos		
Report Format: TP	: Tech. Invs (\$) Others		
Lump Sum / I.B.I: (\$			
Lump oun / non. (9	:Weel:end (\$		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	08/09/2020 09:22
Date Of Accident	06/09/2020 13:00
Exact Location Of Accident	SERANGOON AVE 2
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SBS8429X
Insured/Policyholder	
Name Of Registered Owner	SBS TRANSIT LTD
Co Reg No	1XXXXXXXXXTE01
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65529606
Vehicle Particulars	
Manufacturer	SCANIA
Model	NA
Exact Purpose for which vehicle was being used at time of accident	TRANSPORT
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	ACT
Fleet Policy	NO
Policy Number	D-20095429MFBP
Cover Note Number	
Driver	
Name of Driver	PHUA HENG YONG
NRIC No	SXXXX313F
Date Of Birth	23/08/1965

NRIC No SXXXX313F

Date Of Birth 23/08/1965

Occupation OUTDOOR

Date Of Driving Pass 26/01/1987

Driving Experience 33 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-99999999

Fax Number

Contact Number

EMail Address NOEMAIL

Address **NOADDRESS**

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

NO

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

20 Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

On mentioned date and time, I was driving bus svc 45 in the middle lane of 3 lanes rd as there were vehicles turning left into Serangoon Ave 3 at extreme left lane rd and A m/car (SLR8803K) which plying on my right with intention turning right into Serangoon Ave 3. In the midst it, the said car swerve into my lane and grazed with my bus. As a result, my bus sustained big scratches on right portion. The said car sustained damage on left front. No one was injured. Bus resumed svc after exchanged our particulars.

Attachment(s)

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT Are accident photos available for attachment?

Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number **SLR8803K**

Vehicle Make/Model/Colour

LEFT FRONT DAMAGED

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

Details Of Properties

Contact Number


Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087 Tel: (65) 6253 0233 Email: sales@autoteam.com.sg Co. Reg. No. 201205841K



QUOTATION

Quotation No. Q20091162 7 Sep 2020 Date Net 30 Terms

Quote To **SBS Transit Ltd** Ang Mo Kio Workshop 15 Ang Mo Kio Street 63 Singapore 569117

Attn: Mr Li Ming

S/No	Description	Qty	Unit Price	Amount	
Repair Accident Bus - SBS 8429X					
1.	Supply 3 workers (11 Working Hours)	1 S\$550.00		s\$550.00 /	
:-	Repair Right Side Panel No. 4 & 5				
-	Repair Right Side Body Panel				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:



AT TOTAL



Remark(s) All Material To Be Supplied by SBST

Total

\$\$550.00

This is computer generated. No signature is required.

VAN/LORRY (Rear)

ACTION(AC)

OPenhase(4) Chequist Outline Co
Obtaine Mean Mo

Vehicle No: CRC SUDGY

Rear 1	ortion			
NYC	INC.	Hem	CON	AC
1137	993626	Rear Number Plate		
1138	993627	Rear Number Plate Base		
5044	993628	Rear Number Plate Bracket		

NAC		Hem	CON	AC	Oly
1137		Rear Number Plate			30
2044	993627	Rear Number Plate Base			
1140		Rear Number Plate Bracket			
1141		Rear Number Plate Lamp Rear Bumper			
11-12	993108	Rear Bumper Upper	-		
1143		Rear Bumper Lower			
1144	+	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045					
2046	993079	Rear Bumper Step Garnish			
20-17	1	Rear Crash Bar		-	
1158	994023			_	
1159	993327	Rear End Panel			
1164	993831	Rear LH Taillamp			
1165	993850	Rear LH Taillamp Garnish Rear LH Taillamp Panel	_		
1166	995116	Rear RH Taillamp			
1167		Rear RH Taillamp Rear RH Taillamp Garnish		_	
1168	993859	Rear RH Taillamp Panel			
1169		Rear Apron Panel			
1289	995156	Rear LH Door			
1350				\dashv	
2048		Rear Door Emblem		\neg	
2049	993274	Rear Door Outer Handle			
2051		Rear Door Garnish Rear Door Rubber	-	_	
1291	995194	Rear LH Door Hinge		-4	
1352	995307	Rear RH Door Hinge			
1301	993261			-+	
1362		Rear RH Door Lock	1-1	-+	
2052		Rear Door Glass	+-+	\dashv	
2053		Rear Door Glass Sealant		_	
1248	994729				
1181	994543	Tailgate			
2054	993701	Rear Rubber Stopper Rear Rubber Stopper Bracket			
1182		Tailgate Emblem	1	+	
1183	994643			1	
1185	994545				
1193	994602	<u> </u>			
1194	994606		1	_	\Box
1195	994604		1	-	
2056	994607	¥	╂──╂	+	
1197	9946397		1		
1198	994651			\dashv	\dashv
1199	994611	Tailgate Hinge		7	\neg
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm		\bot	
2058		Rear Wiper Blade	-	-	_
2059 2060	993997	Rear Wiper Motor	 -		
1204		Rear Floor Panel Spare Tyre	 -	-	
2061	993785	Spare Tyre Bracket		-	-
1212	993364	Rear Exhaust Pipe	-	+	-
1214	993361	Rear Exhaust Mounting	-		
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member		_	
Il			ll_	L_	

		Tehlele No: SBS 842	29X		
NYC		Item		NA	CQ
2062		Rear Sidegate		~	7
2063	994225	Rear Sidegate Lock		_ _	+
2064	993749	Rear Sidevate Hinge			1
2065	994226	Sidegate Lower Panel		1	_
2066					
2067		Side Cover Hook		T	
2068		Side Panel No.4,5	R	2	
2069		Side Step Panel Stopper			
2070	992857	Right Body Panel	R	1	_
2071	992866	Rear Body Panel Inner	+'>		+
2072	995329	Sliding Door LH	+	1	
2073	995328	Sliding Door RH		1	1-
2074	994295	Sliding Door Handle			1
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077		Sliding Door Bottom Roller		_	
2078 2079		Sliding Door Top Roller		1	
	004245	Sliding Door Rail	1_	1_	-
2000	994315	Sliding Door Stepboard	-	1	
2081	994316	Sliding Door Stepboard Garnish		L	
2122A	993621	Rear LH Mudflap		_	
		Rear LH Wheel Rim	↓	1_	_
\$1020	005065	Rear LH Rim Cover Rear LH Tyre	<u> </u>	<u> </u>	└
11234	993622	Rear RH Mudflap	├	-	├
11235	993934	Rear RH Wheel Rim	+	\vdash	+
1236	994025	Rear RH Rim Cover	+	+	-
11237	995065	Rear RH Tyre		1	
直252	992179	Fuel Tank			
1258	992184	Fuel Tank Bracket			
11186	990247	Sticker colour	Nec	2	
					
					
	•				
				\vdash	
 					
					[
				\dashv	
				-	
			ا		I

Assessor: Sun Pin isto of trems:_____