



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
WEI LEE MOTOR WORKS			Ref: CS/TP21000283/Kvd3e2	
BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32			Date: 12/01/2021	
SINGAPORE 575644				
ON BEHALF OF HAN YEE YEN			Code: TP389	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SDV 8850Y
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		06/01/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200 A	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WDD2040412A159138	Colour	DARD BLUE	
Odometer	114092 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	9 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	9 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	4 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2020	Inspection Date	06/01/2021	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	