

ASS. REC. BY:

REF:

LPC/ 21000307/K7

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s KK HIN

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 828k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 9/15 Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 Broken Flat

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Veh No: GBB 9603S Yr Regn: 10, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Carter c.c. 2977Colour: White AC: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FB 70BBA 20035Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F. Bearway 195R15X8
R. Dunlop - (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 3/1/21

Survey held at

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 8/1/2021

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

① IN LXX



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z/20/VC00/106952
Accident Date : 03-Jan-2021

No. : 31610

Date : 07-Jan-2021

Our Ref : 020639 / SANDRA

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

Not Withheld
16 days
Permy After Paint
Ex @ 600k

ESTIMATED COST OF REPAIR FOR MIT FB70BB1SRDEA(2977cc)(2010) GBB9603S
=====

1 pc	n/s front door	Bu	950.00	c	✓
1 pc	n/s front door outer arch garnish	Bu	150.00	c	✓
2 pcs	n/s front door hinges (top/ lower)	Bu	240.00	c	✓
		@ S\$120.00			
1 pc	n/s front door checker	Bu	115.00	c	✓
1 pc	n/s front door step garnish	CM	240.00	c	✓
1 pc	n/s front door weatherstrip	CM	140.00	c	✓
1 pc	n/s front door frame weatherstrip	CM	130.00	c	✓
1 pc	n/s front door glass	Bu	165.00	c	✓
1 pc	n/s front door glass channel	Dit	190.00	c	✓
1 pc	n/s front door glass railing	Dit	80.00	c	✓
1 pc	n/s front door regulator and motor	Bu	540.00	c	✓
1 pc	n/s front door outer moulding	Bu	80.00	c	✓
1 pc	n/s front door outer vertical garnish - front	Miy	100.00	c	✓
1 pc	n/s front door lock	Tu	265.00	c	✓
1 pc	n/s front door lock catch	Nd	45.00	c	✓
1 pc	n/s front door lock switch	CM	65.00	c	✓
1 pc	n/s front door outer pull handle	Dit	80.00	c	✓
1 pc	n/s front door inner trim- board	CM	580.00	c	✓
1 pc	n/s front door inner pull handle	Dit	120.00	c	✓

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 2
No. : 31610

1 pc	n/s front door inner handle railing	Diy	180.00	c	✓
1 pc	n/s front door power window control panel	my cm	360.00	c	✓
1 pc	n/s front door outer vertical garnish - rear	my	55.00	c	✓
1 pc	n/s door 'A' pillar	Ry	1,050.00	c	✓
1 pc	n/s door 'A' pillar inner	Ry	950.00	c	✓
1 pc	n/s wingmirror - big	CM	80.00	c	✓
1 pc	n/s wingmirror - round	my	60.00	c	✓
1 pc	n/s wingmirror - stay	Ry	180.00	c	✓
1 pc	n/s wingmirror stay cap cover	my	35.00	c	✓
1 pc	n/s wingmirror stay inner cover	my	55.00	c	✓
1 pc	front wiper panel garnish-big	way	175.00	c	✓
1 pc	n/s front wiper panel garnish -small	my	45.00	c	✓
1 pc	front panel	Ry	1,000.00	c	✓
1 pc	n/s front corner panel	Ry	240.00	c	✓
2 pcs	headlamp (LH & RH)	MS my CM @ S\$340.00	680.00	c	✓
2 pcs	headlamp lower rubber lid (LH & RH)	@ S\$ 9.50	19.00	c	✓
2 pcs	front side reflector (LH&RH)	MS CM @ S\$ 65.00	130.00	c	✓
2 pcs	front signal lamp (LH & RH)	@ S\$130.00 MS Bo	260.00	c	✓
1 pc	front windscreen glass	Shotton	480.00	c	✓
1 pc	front windscreen glass rubber	Rd	195.00	c	✓
1 pc	n/s front windscreen pillar inner garnish	CM	195.00	c	✓
1 pc	wiper washer tank and motor		145.00	c	?
1 pc	n/s front windscreen pillar inner handle	Sm	140.00	c	x
1 pc	o/s front door	R	950.00	c	x
1 pc	o/s front door lock	R	265.00	c	x
1 pc	roof top panel reinforcement-front	Ry	600.00	c	✓
1 pc	roof top trim lining	Reform	1,200.00	c	✓
1 pc	dashboard assy	Brilcm	1,550.00	c	✓

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 3
No. : 31610

1 pc	dashboard reinforcement		195.00	c	?
1 pc	n/s dashboard glove compartment		260.00	c	✓
1 pc	dashboard centre console		380.00	c	✓
1 pc	dashboard air con control panel		1,800.00	c	?
1 pc	dashboard meter		2,400.00	c	?
1 pc	o/s dashboard meter console		260.00	c	✓
1 pc	o/s dashboard side garnish		125.00	c	✓
4 pcs	dashboard air con lourves	@ S\$ 85.00	340.00	c	?
4 pcs	dashboard air con lourves inner duct	@ S\$100.00	400.00	c	?
1 pc	dashboard inner fuses & relay box		480.00	c	?
1 pc	n/s dashboard lower garnish		165.00	c	✓
1 pc	front hand gear lever cover		265.00	c	?
2 pcs	front wiper blade (LH & RH)	@ S\$ 95.00	190.00	c	x
1 pc	air con blower		1,650.00	c	?
	air con cooling coil				
	air con heater unit				
1 pc	air con discharge pipe		340.00	c	?
1 pc	air con suction pipe		340.00	c	?
1 pc	radiator		1,250.00	c	?
1 pc	radiator fan cowling		165.00	c	?
1 pc	radiator fan blade		140.00	c	?
1 pc	radiator fan clutch		340.00	c	?
2 pcs	engine mounting (LH & RH)	@ S\$130.00	260.00	c	?
1 pc	gearbox mounting		110.00	c	?
			27,404.00		
Add 15% :			4,110.60		
			31,514.60		
1 pc	n/s front door ROC sticker		15.00	sn	✓
1 pc	n/s front door inner speaker		120.00	sn	?
1 pc	front panel heat insulation		150.00	sn	?
1 pc	ERP bracket		26.00	sn	✓

Con't Page 4 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 4
No. : 31610

1 pc o/s front door ROC sticker
1 pc dashboard radio headset

na 15.00 sn X
240.00 sn 7

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

2,400.00 2000

To remove and renew front wind-
screen glass and conduct water
leak test.

100.00 601

To remove aircon condenser, pipes
and driers. Vacuum and recharge gas

100.00 ✓

To remove door's fittings

160.00 601

To conduct front wheel alignment
test.

na 80.00 X

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

280.00 220

To putty and respray on affected
portions.

1,400.00 1200

To focus headlamps. To check front
wiring and lighting operation.

50.00 201

Total : S\$36,650.60
=====

Singapore Dollars Thirty Six Thousand Six Hundred
and Fifty and Cents Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Back to OneMotoring

Acquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	668D
Vehicle Details	
Vehicle No.:	GB896035
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	FB70881SRDEA
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	4M42A80685
Chassis No.:	FB7088A20235
Maximum Power Output:	-
Open Market Value:	\$28,348.00
Original Registration Date:	12 Oct 2010
First Registration Date:	12 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$1,418.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$11,975.00
COE Rebate Amount:	\$11,349.00
Total Rebate Amount:	\$11,349.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 04 Jan 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/01/2021 21:25 (SGT)
Date of Accident 03/01/2021 15:45 (SGT)
Exact Location of Accident CTE, Singapore
Additional Location Information CTE TOWARDS CITY LAMP POST 245
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB9603S

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TROPICAL ENVIRONMENT PTE LTD
Company Reg No 1XXXXX668D
Email Address ADMIN@TROPICPLANNERS.COM.SG
Mobile Phone No (Phone) +65-67620500
Alternative Phone No (Office) +65-67620500

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Fb70bb1srdea
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company Lonpac
Type of Coverage Comprehensive
Fleet Policy No
Policy Number Z/20/VC00/106952
Cover Note Number -

DRIVER

Name of Driver PERIYATHAMBI MUNIYAPPAN
Passport No/FIN GXXXX345U
Date Of Birth 30/07/1983
Occupation Indoor

Date Of Driving Pass	13/11/2017
Driving experience	3 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91303796
Alt. Phone Number	-
Email Address	ADMIN@TROPICPLANNERS.COM.SG
Address	C/O 60 JALAN LEKAR
Address complement	-
Postcode	698947
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	SALAM ABDUS
Gender	Male

PASSENGER 2

Name	MOJAMMEL
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Paya Lebar Neighbourhood Police Post
Police Station Address	Blk 114 Hougang Avenue 1 #01-1270 Singapore 530114
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7386B
Vehicle Manufacturer	-

C = SJD4390H. CTE exit Serangdon

As per Police Report ,

I/We declare the foregoing particulars are true in every respect.





SINGAPORE POLICE FORCE

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999



T/20210103/2054

1 of 4

Report No. T/20210103/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/01/2021 17:07	Vide Report No.: A/20210103/0098	Station Diary No.: 32
--	-------------------------------------	--------------------------

Name of Informant: PERIYATHAMBI MUNIYAPPAN			Address:		
ID Type / ID No.: FIN NO / G7928345U			Contact No.: Home/Office: Mobile: 91303796		
Nationality: INDIAN			Email:		
Sex: Male	Age: 37	Date of Birth: 30/07/1983	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Civil engineering/Building construction labourer			Driving Licence Information: Class: Date of Expiry:		

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/01/2021 15:45	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Lamp Post Number: 245				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Vehicle No	Type	Make	Model	Year	Damage	Count
GBB9603S	Lorry				Seriously Damaged	2
SJD4390H	Car				Slightly Damaged	0
YM7386B	Lorry				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20210103/2054

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

2 of 4

Report No. T/20210103/2054

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	SALAM ABDUS	ID No.	G6986167P
Related Vehicle	GBB9603S (Lorry)	Contact No.	98955142
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	PERIYATHAMBI MUNIYAPPAN	ID No.	G7928345U
Related Vehicle	GBB9603S (Lorry)	Contact No.	91303796
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	MOJAMMEL	ID No.	G2484521X
Related Vehicle	GBB9603S (Lorry)	Contact No.	86495307
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 03/01/2021 at about 1545hrs, I was traveling along CTE towards PIE along with 2 more passenger in my lorry (GBB9603S).

A lorry (YM7386B) was initially driving in front of me. All of a sudden, the lorry jammed braked. I tried to brake but could not stop in time. As such, my lorry front side collided into the lorry rear.

There was a vehicle (SJD4390H) in front of the lorry (YM7386B) when the incident happened. The vehicle suffered some scratches on the rear. But I am not sure if the lorry in front of me had already collided into