



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21000315/Utd3e2	Date: 14/01/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGG 6545K	Veh. Inspected	GBJ 8441G
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10008524/CH	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	07/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JN1YAAM20Z0000359	Colour	WHITE
	Odometer	16188 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	165/80 R14	NEXEN	6 mm
	L/H Front Tyre	165/80 R14	NEXEN	6 mm
	R/H Rear Tyre	165/80 R14	NEXEN	6 mm
	L/H Rear Tyre	165/80 R14	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/12/2020	Inspection Date	12/01/2021
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks				
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	