

ASS. REC. BY:

*Steve*

REF:

*CS/AIG 21000378/EA03*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 1900254065

Claims No. 1371093144SG


Sum Insured: \_\_\_\_\_ Excess: 0/-

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Turn Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SCU 7887R

Yr Regn: 12/12/19

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: KIA Stonic c.c. 998

Colour: White A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ N

Sp. Reading 21228 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ N

Eng/No: \_\_\_\_\_

C/No: KNAD 6811VL 6346850

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 6/1/21 D.O.I. 8/1/21

Survey held at Cycle & Carriage

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MR-79K

08/01/21 @ 1.50pm revert to AIG via Merimen

08/01/21 @ 6.27pm Kok Chong informed C/A via Merimen

11/01/21 @ 9.14am Informed C&C C/A & ex.\$0/- by email.

20/01/21 @ 5.34pm confirmed with Ms Loi final fig \$1632, 3 days (Red \$3366.40, 67%)

Date/Time, File, Pass to?

☐ : Prelim. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (%) \_\_\_\_\_

☐ : Weekend (\$) \_\_\_\_\_

Approved:

MER-OD

Signature / Date

1632



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #08-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name LCV11677/SENG BOON TECK<br>Reg No/Reg Date SCU7887R*KC17/ 12/12/201<br>Date In/Mileage / 21228<br>Chassis No KNAD6811VL6346850<br>Engine No G3LCKP111753<br>Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF<br>Colour/Trim UD CLEAR WHITE / WK SATURN BLACK |

| Account No   | Terms  | Date/Time Printed | CSE | Operator      | WIP No |            |       |         |
|--|--------|-------------------|-----|---------------|--------|------------|-------|---------|
| LAX00000   | Credit | 07/01/2021/ 16:40 | QUD | 247 / DonBong | 26943  |            |       |         |
| Description of Goods / Services  |        |                   |     |               | Qty    | Unit Price | Disc% | Amount  |
| E PNT88000<br>RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,<br>REPAIR REAR END PANEL     |        |                   |     |               | 400    |            |       | 1200.00 |
| E PNT88000<br>REMOVE AND INSTALL PARKING ASSIST  |        |                   |     |               | ?      |            |       | 60.00   |
| E PNT88000<br>REMOVE AND INSTALL REAR BOOT GARNISH TO FACILITATE<br>REPAIR WORK              |        |                   |     |               | X      |            |       | 120.00  |
| E PNT98000<br>PAINT WORK SPRAY REAR END PANEL, REAR BUMPER<br>AND AFFECTED PORTION           |        |                   |     |               |        |            |       | 1050.00 |
| A 54900099<br>CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM                                     |        |                   |     |               | ?      |            |       | 30.00   |
| M SUNDRY<br>PERFORM RUST PREVENTION  |        |                   |     |               |        |            |       | 80.00   |
| A 10028901<br>TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST |        |                   |     |               |        |            |       | 120.00  |
| M SUNDRY<br>SUPPLY REAR NUMBER PLATE WITH FRAME  |        |                   |     |               |        |            |       | 50.00   |
| M SUNDRY<br>SUNDRIES   |        |                   |     |               | ?      |            |       | 50.00   |
| M BRACKET ASSY-RR BUMPER SIDE, LH  |        |                   |     |               | 1.00   | 27.00      | 20.00 | 21.60   |
| M BRACKET ASSY-RR BUMPER SIDE, RH  |        |                   |     |               | 1.00   | 27.00      | 20.00 | 21.60   |
| M ANTENNA ASSY-SMARTKEY  |        |                   |     |               | 1.00   | 32.00      | 20.00 | 25.60   |
| M BRACKET-RR BEAM UPR MTG  |        |                   |     |               | 2.00   | 7.00       | 20.00 | 11.20   |
| M BRACKET-RR BEAM LWR MTG, LH  |        |                   |     |               | 1.00   | 7.00       | 20.00 | 5.60    |
| M BRACKET-RR BEAM LWR MTG, RH  |        |                   |     |               | 1.00   | 5.00       | 20.00 | 4.00    |
| M STAY-RR BUMPER LH  |        |                   |     |               | 1.00   | 55.00      | 20.00 | 44.00   |
| M STAY-RR BUMPER RH  |        |                   |     |               | 1.00   | 55.00      | 20.00 | 44.00   |
| M WIRING HARNESS-BWS EXT   |        |                   |     |               | 1.00   | 245.00     | 20.00 | 196.00  |
| M CLIP   |        |                   |     |               | 10.00  | 1.00       | 20.00 | 8.00    |
| M COVER-RR BUMPER LWR (Black) / CR4  |        |                   |     |               | 1.00   | 366.00     | 20.00 | 292.80  |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE &amp; CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #08-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name LCV11677/SENG BOON TECK<br>Reg No/Reg Date SCU7887R*KC17/ 12/12/201<br>Date In/Mileage / 21228<br>Chassis No KNAD6811VL6346850<br>Engine No G3LCKP111753<br>Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF<br>Colour/Trim UD CLEAR WHITE / WK SATURN BLACK |

| Account No                      | Terms                            | Date/Time Printed | CSE | Operator      | WIP No |            |       |        |
|---------------------------------|----------------------------------|-------------------|-----|---------------|--------|------------|-------|--------|
| LAX00000                        | Credit                           | 07/01/2021/ 16:40 | QUD | 247 / DonBong | 26943  |            |       |        |
| Description of Goods / Services |                                  |                   |     |               | Qty    | Unit Price | Disc% | Amount |
| M                               | MOULDING ASSY-RR BUMPER SIDE,L   |                   |     |               | 1.00   | 152.00     | 20.00 | 121.60 |
| M                               | MOULDING ASSY-RR BUMPER SIDE,R   |                   |     |               | 1.00   | 152.00     | 20.00 | 121.60 |
| M                               | CAP-RR HOOK / CR                 |                   |     |               | 1.00   | 5.00       | 20.00 | 4.00   |
| M                               | SKID PLATE-RR BUMPER (S/L) - CR  |                   |     |               | 1.00   | 122.00     | 20.00 | 97.60  |
| M                               | CLIP / MC                        |                   |     |               | 10.00  | 1.00       | 20.00 | 8.00   |
| M                               | ULTRASONIC SENSOR ASSY-BWS       |                   |     |               | 1.00   | 189.00     | 20.00 | 151.20 |
| M                               | ULTRASONIC SENSOR ASSY-BWS       |                   |     |               | 1.00   | 189.00     | 20.00 | 151.20 |
| M                               | ULTRASONIC SENSOR ASSY-BWS       |                   |     |               | 1.00   | 189.00     | 20.00 | 151.20 |
| M                               | ULTRASONIC SENSOR ASSY-BWS       |                   |     |               | 1.00   | 189.00     | 20.00 | 151.20 |
| M                               | TRIM ASSY-RR TRANSVERSE X        |                   |     |               | 1.00   | 55.00      | 20.00 | 44.00  |
| M                               | LAMP ASSY-REAR FOG & R/REFL LH X |                   |     |               | 1.00   | 111.00     | 20.00 | 88.80  |
| M                               | LAMP ASSY-REAR FOG & R/REFL RH X |                   |     |               | 1.00   | 111.00     | 20.00 | 88.80  |

Estimate

SURVEYOR NAME: Steve (LKK) 8/1/21, 10.00 am

SURVEYOR SIGNATURE: OO-NM Aut

DATE: Expires - ?

REMARKS: P/P

By Bel SM  
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on Net 4,613.60 322.95

Total Payable 4,936.55

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 07/01/2021 16:44 (SGT)  
Date of Accident ..... 06/01/2021 07:41 (SGT)  
Exact Location of Accident ..... AYE, Singapore  
Additional Location Information ..... AYE TOWARDS TUAS AFTER SHOPEE BUILDING, UNDER  
BUONA VISTA FLYOVER  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SCU7887R  
INSURED/POLICYHOLDER  
Is company? ..... No  
Name Of Registered Owner ..... SENG BOON TECK  
NRIC No ..... SXXXX349I  
Email Address ..... STEVEN@WORKGROUPSYSTEM.COM  
Mobile Phone No ..... (Phone) +65-98163136  
Alternative Phone No ..... +65-98163136

### VEHICLE PARTICULARS

Manufacturer ..... Kia  
Model ..... Stonic  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car

### INSURANCE COMPANY

Name of Insurance Company ..... AIG  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 1900254065  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... SENG RUI HAO, EUGENE  
NRIC No ..... SXXXX708A  
Date Of Birth ..... 01/02/1993

Occupation .....  
 Date Of Driving Pass .....  
 Driving experience .....  
 Gender .....  
 Mobile Number .....  
 Alt. Phone Number .....  
 Email Address .....  
 Address .....  
 Address complement .....  
 Postcode .....  
 Is the driver the policyholder? .....  
 If No, Relationship of the Driver with the Insured .....  
 Does Driver Own Other Vehicles? .....  
 Vehicle Registration Number of Other Vehicle Owned by Driver .....  
 Insurance Company of Other Vehicle Owned by Driver .....

Indoor  
 10/04/2012  
 8 YEARS AND 9 MONTHS  
 Male  
 (Phone) +65-91771520  
 -  
 SENG.EUGENE93@GMAIL.COM  
 476B UPPER SERANGOON VIEW #08-526  
 -  
 532476  
 No  
 Child  
 No  
 -  
 -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
 Weather Conditions .....  
 Road Surface .....

Collision - Head to Rear  
 Clear  
 Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
 Number of vehicles involved in the accident .....  
 Was anybody injured in the Accident? .....  
 Was any injured conveyed to hospital by ambulance? .....  
 Was any other material or property damaged? .....  
 Number of Passengers (Including Driver) .....  
 Has the driver been approached by unknown person(s) .....  
 soliciting/offering accident claims assistance? .....

No  
 2  
 No  
 -  
 Yes  
 1  
 Yes

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
 Was notice of intended Prosecution given? .....  
 If yes, against whom? .....

No  
 No  
 -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment? .....  
 Was there any video captured by Car Camera? .....  
 Was there any audio recorded? .....

Yes  
 Yes  
 No

#### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number .....  
 Vehicle Manufacturer .....  
 Vehicle Model .....  
 Vehicle Variant .....  
 Vehicle Colour .....  
 Vehicle Category .....  
 Name of Driver .....  
 Contact Number .....  
 Address .....  
 Address complement .....  
 Postcode .....

SMU9401C  
 Nissan  
 -  
 -  
 Black  
 Private car  
 WOO YUN SUM  
 (Phone) +65-97278717  
 -  
 -  
 -

Insurance Company Name ..... NTUC  
Amount Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -



## SKETCH PLAN

### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan




### Circumstances of the Accident


traffic in front slowed down and came to a complete stop. I too slowed down and was preparing to stop when the car behind hit me and I was launched forward.

### **Declaration**

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

 07/01/2021 3.20pm

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



# CERTIFICATE OF INSURANCE

## AUTO PROTECTOR PRIVATE VEHICLE

**Policyholder** : SENG BOON TECK  
**Period of Insurance** : 12 Dec 2019 To 11 Dec 2021  
**Engine No.** : G3LCKP111753  
**Chassis No.** : KNAD6811VL6346850

**Vehicle No.** : SCU7887R  
**Policy No.** : 1900254065  
**Endorsement No.** :  
**Issued Date** : 17 Dec 2019

### ABOUT THE COVER

**Make/Model** : KIA Stonic  
**Engine Capacity/Tonnage** : 998.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2019  
**Insuring with COE/PAF** : Yes

#### Person or Classes of Persons Entitled to Drive\*

- a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition  
**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

**Section 1**  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

**Section 2**  
 Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess** (where applicable)

SENG BOON TECK - \$600 (Own Damage), \$600 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622200

C&CKICP2 - ALTHAM

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

SSCHMG

1002841046/JAC4/Decal